



AV53GUH

report date: 2024-03-29

General information

Make	FORD
Model	FUSION 16V ZETEC
Colour	Grey
Year of manufacture	-
Top speed	104 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg



**MOT history**

MOT #20	2020-11-17 16:01
MOT test number	387811640301
Result	✓ Passed
Next expiry date	2021-11-16
Advice	Central Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #19	2020-11-17 11:34
MOT test number	903427610938
Result	✗ Failed
Fail	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Central Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Minor	Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Minor	Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #18	2019-11-12 16:19
MOT test number	162773982236
Result	✓ Passed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #17**

2019-11-12 16:19

MOT test number

345138203867

Result**✗ Failed****Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #16**

2018-11-14 13:17

MOT test number

971997194143

Result**✓ Passed****Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Coolant leak**MOT #15**

2018-11-14 13:17

MOT test number

472923080849

Result**✗ Failed****Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Coolant leak**Pass with rectification** Offside Rear fog lamp not working (4.5.1 (a) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #14** 2017-11-14 15:12**MOT test number** 727922395754**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit 2.9mm (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit 1.8mm and both edges worn bald (4.1.E.1)**MOT #13** 2017-11-14 15:12**MOT test number** 815964415300**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit 1.8mm and both edges worn bald (4.1.E.1)**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Advice** Offside Front Tyre worn close to the legal limit 2.9mm (4.1.E.1)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**MOT #12** 2016-11-01 15:01**MOT test number** 265346779300**Result** ✓ Passed**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #11** 2016-11-01 15:01**MOT test number** 109970289124**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)

**MOT #10** 2015-11-06 12:49**MOT test number** 439148868371**Result** ✓ Passed**Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #9** 2014-10-09 10:34**MOT test number** 617902984244**Result** ✓ Passed**Notice** Tread cracking on the near side rear tyre**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #8** 2013-10-14 11:15**MOT test number** 715607883229**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2012-09-13 12:29**MOT test number** 558187452289**Result** ✓ Passed**MOT #6** 2011-09-01 13:46**MOT test number** 917714741263**Result** ✓ Passed**MOT #5** 2010-09-17 10:12**MOT test number** 450280960222**Result** ✓ Passed



MOT #4	2009-09-17 10:39
MOT test number	594180769223
Result	✓ Passed

MOT #3	2008-09-12 10:35
MOT test number	763016558285
Result	✓ Passed

MOT #2	2007-09-14 12:17
MOT test number	812627757214
Result	✓ Passed

MOT #1	2006-09-15 17:00
MOT test number	364158956405
Result	✓ Passed

Advice

 Inner Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2003-09-19
Last registration	2020-11-17
Complete history	See info



Registration #1	2003-09-19	13 mi
Registration #2	2006-09-15	16.096 mi
Registration #3	2007-09-14	20.360 mi
Registration #4	2008-09-12	24.242 mi
Registration #5	2009-09-17	27.703 mi
Registration #6	2010-09-17	31.565 mi
Registration #7	2011-09-01	35.609 mi
Registration #8	2012-09-13	38.517 mi
Registration #9	2013-10-14	42.042 mi
Registration #10	2014-10-09	45.307 mi
Registration #11	2015-11-06	47.416 mi
Registration #12	2016-05-20	51.277 mi
Registration #13	2016-05-20	51.277 mi
Registration #14	2016-05-20	51.277 mi
Registration #15	2016-05-20	51.277 mi
Registration #16	2016-05-20	51.277 mi
Registration #17	2016-05-20	51.277 mi
Registration #18	2016-05-20	51.277 mi
Registration #19	2016-05-20	51.277 mi
Registration #20	2016-05-20	51.277 mi
Registration #21	2016-05-20	51.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1463 mm
Length	3917 mm
Wheel base	2486 mm
Kerb weight	1076 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	3E55488