



report date: 2024-03-28

General information

Make	SUZUKI
Model	ALTO SZ4
Colour	Black
Year of manufacture	2009
Top speed	96 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	B





MOT history

MOT expiry date	2021-01-02
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	21
Total items failed	7

MOT #12 2019-06-29 13:57

MOT test number 607552621473

Result ✓ Passed

Next expiry date 2021-01-02

- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11 2018-07-03 13:32

MOT test number 627216942070

Result ✓ Passed

- Advice** Corrosion under vehicle various places

**MOT #10**

2017-07-03 14:46

MOT test number

922386697439

Result

✓ Passed

Advice Nearside Rear coil spring corroded (2.4.C.1b)**Advice** Offside Front Lower Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Nearside Front wheel trim missing**MOT #9**

2017-07-03 13:26

MOT test number

783747969451

Result

✗ Failed

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively split (8.2.2)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Nearside Front wheel trim missing**Advice** Offside Front Lower Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**MOT #8**

2016-06-30 08:20

MOT test number

713240611043

Result

✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2016-06-30 08:20**MOT test number** 661587786424**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2015-07-01 12:43**MOT test number** 448962085165**Result** ✓ Passed**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**MOT #5** 2015-07-01 12:43**MOT test number** 765382585155**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Pass with rectification** Offside Headlamp aim too low (1.8)**Pass with rectification** Rear registration plate insecure (6.3.1b)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**MOT #4** 2014-07-03 14:46**MOT test number** 645674584177**Result** ✓ Passed



MOT #3	2013-06-27 09:11
MOT test number	406868173162
Result	✓ Passed
MOT #2	2012-06-28 13:14
MOT test number	407990382138
Result	✓ Passed
MOT #1	2012-06-28 11:18
MOT test number	487590782187
Result	✗ Failed
Fail	Brakes imbalanced across an axle (3.7.B.5b)
Fail	Front Headlamp aim too low (1.8)



Tax & MOT check

✕
Untaxed

Tax expired:
29 December 2020

✕
MOT

Expired:
2 January 2021

Tax status	Expired at 29 December 2020
Days left	1217 days too late
MOT expiry date	2 January 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	DN09WKW
Plate since	2019-09-29
Current registration	DN09WKW
Plate since	2019-09-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2009-07-02
Last registration	2019-06-29
Complete history	See info



Registration #1	2009-07-02	22 mi
Registration #2	2012-06-28	35.374 mi
Registration #3	2012-06-28	35.374 mi
Registration #4	2013-06-27	46.101 mi
Registration #5	2014-07-03	59.242 mi
Registration #6	2015-07-01	66.831 mi
Registration #7	2019-06-29	75.277 mi
Registration #8	2019-06-29	75.277 mi
Registration #9	2019-06-29	75.277 mi
Registration #10	2019-06-29	75.277 mi
Registration #11	2019-06-29	75.277 mi
Registration #12	2019-06-29	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	see crash video



Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	K10BN 1009612