



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	107 ACTIVE
Colour	Red
Year of manufacture	2013
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-06-18
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-05-20
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	17
Total items failed	7

MOT #16 2023-05-10 12:20

MOT test number 196284175368

Result ✓ Passed

Next expiry date 2024-05-20

Advice Offside Rear Brake pipe corroded, covered in grease or other material front to rear at rear flex hose corroded (1.1.11 (c))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material front to rear at rear flex hose corroded (1.1.11 (c))

Advice Front Exhaust mounting defective front mounting corroded (6.1.2 (a))

Advice Offside Rear Tyre slightly damaged/cracking or perishing in tread (5.2.3 (d) (ii))

MOT #15 2023-05-09 14:44

MOT test number 315301390896

Result ✗ Failed

Fail Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn on both edges and badly cracked on outer edge (5.2.3 (e))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material front to rear at rear flex hose corroded (1.1.11 (c))

Advice Front Exhaust mounting defective front mounting corroded (6.1.2 (a))

Advice Offside Rear Tyre slightly damaged/cracking or perishing in tread (5.2.3 (d) (ii))

Advice Offside Rear Brake pipe corroded, covered in grease or other material front to rear at rear flex hose corroded (1.1.11 (c))

**MOT #14** 2022-05-21 09:20**MOT test number** 368211917989**Result** ✓ Passed**MOT #13** 2022-05-20 13:14**MOT test number** 905610895296**Result** ✗ Failed

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #12 2021-06-24 15:02**MOT test number** 899040913104**Result** ✓ Passed**MOT #11** 2021-06-23 07:54**MOT test number** 142846966608**Result** ✗ Failed

Fail Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #10 2021-02-23 10:41**MOT test number** 698808588963**Result** ✓ Passed**MOT #9** 2021-02-23 10:41**MOT test number** 125742808740**Result** ✗ Failed

Pass with rectification Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #8** 2020-03-11 11:53**MOT test number** 433571992249**Result** ✓ Passed**MOT #7** 2019-09-02 14:31**MOT test number** 816371781145**Result** ✓ Passed**Advice** Brake pipe corroded, covered in grease or other material both front to rears at rear section (1.1.11 (c))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #6** 2019-09-02 09:27**MOT test number** 733950302336**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Brake pipe corroded, covered in grease or other material both front to rears at rear section (1.1.11 (c))**MOT #5** 2018-08-14 08:29**MOT test number** 561197446364**Result** ✓ Passed**MOT #4** 2018-08-14 08:29**MOT test number** 517941609077**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))



MOT #3	2017-08-12 09:26
MOT test number	358276945656
Result	✓ Passed
Advice	Tyre worn close to the legal limit both rear (4.1.E.1)

MOT #2	2016-08-19 09:40
MOT test number	114245748781
Result	✓ Passed

MOT #1	2015-08-20 13:51
MOT test number	392387112684
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
20 May 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	20 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2013-01-10
Last registration	2023-05-10
Complete history	See info



Registration #1	2013-01-10	19 mi
Registration #2	2015-08-20	24.560 mi
Registration #3	2016-08-19	31.577 mi
Registration #4	2017-08-12	40.819 mi
Registration #5	2018-08-14	53.574 mi
Registration #6	2018-08-14	53.574 mi
Registration #7	2019-09-02	64.758 mi
Registration #8	2019-09-02	64.758 mi
Registration #9	2020-03-11	67.418 mi
Registration #10	2020-03-11	67.418 mi
Registration #11	2020-03-11	67.418 mi
Registration #12	2020-03-11	67.418 mi
Registration #13	2020-03-11	67.418 mi
Registration #14	2020-03-11	67.418 mi
Registration #15	2020-03-11	67.418 mi
Registration #16	2020-03-11	67.418 mi
Registration #17	2020-03-11	67.418 mi
Registration #18	2020-03-11	67.418 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	see crash video



Dimensions & weight

Width	1855 mm
Height	1470 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Engine number	7381315
---------------	---------