





report date: 2024-03-28

#### General information

Make	TOYOTA
Model	AURIS T SPIRIT
Colour	Blue
Year of manufacture	2012
Top speed	111 mph
0 - 60 mph	11.4 seconds
Gearbox	1 speed CVT

## Engine & fuel consumption

Power	134 BHP
Max. torque	142 Nm at 4.400 rpm
Engine capacity	1.797 сс
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	70.6 mpg
Consumption extra urban	70.6 mpg
Consumption combined	70.6 mpg
CO2 emission	93 g/km
CO2 label	A



CarCheck.co.uk page 1/14



report date: 2024-03-28

# Internet history

#### Entry 1

Date 2021-02-04


Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

## **MOT** history

MOT expiry date	2025-02-10
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	29
Total items failed	11

MOT #15	2024-02-09 08:52
MOT test number	623633720075
Result	✓ Passed
Next expiry date	2025-02-10
Advice Nearside Front Suspension arm pin or bush worn but not resulting in bush (5.3.4 (a) (i))	excessive movement tca
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously wea	akened (1.1.14 (a) (ii))
Advice Offside Rear Tyre slightly damaged/cracking or perishing cracking and slightly out of shape (5.2.3 (d) (ii))	
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement tca bush (5.3.4 (a) (i))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))	and slightly out of shape

CarCheck.co.uk page 3/14



report date: 2024-03-28

**MOT #14** 2024-02-07 14:10

**MOT test number** 800585631844

**Result** X Failed

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking and slightly out of shape (5.2.3 (d) (ii))

**Fail** Offside Front Inner Tyre has a tear, caused by separation or partial failure of its structure marked in yellow (5.2.3 (d) (ii))

Fail Front Service brake excessively fluctuating (1.2.1 (e))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement tca bush (5.3.4 (a) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing cracking and slightly out of shape (5.2.3 (d) (ii))

**Fail** Nearside Front Inner Tyre has a tear, caused by separation or partial failure of its structure marked in yellow (5.2.3 (d) (ii))

Fail Horn not working (7.7 (a))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement tca bush (5.3.4 (a) (i))

**MOT #13** 2023-01-26 09:54

MOT test number 158386031377

Result 

Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement tca

bush (5.3.4 (a) (i))

CarCheck.co.uk page 4/14



Advice

SB62YZR

report date: 2024-03-28

MOT test number
969810766789

Result

Fail Offside Front Brake pipe excessively corroded (1.1.11 (c))

Advice Front Service brake fluctuating, but not excessively (1.2.1 (e))

Fail Offside Rear Brake pipe excessively corroded from hose to caliper (1.1.11 (c))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement tca bush (5.3.4 (a) (i))

MOT #11

MOT test number

966012922722

Result

Advice (c))

Advice Offside Rear Brake pipe corroded, covered in grease or other material from hose to caliper (1.1.11

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT test number

S15838458878

Result

Advice Offside Rear Brake pipe corroded, covered in grease or other material from hose to caliper (1.1.11 (c))

Fail Horn not working (7.7 (a))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #9

MOT test number

Result

2021-02-11 09:07

287607148487

✓ Passed

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #8 2019-11-07 09:18

**MOT test number** 397709519266

**Result** ✓ Passed

MOT #7 2018-12-13 14:24

**MOT test number** 531108517533

**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Minor Horn not working properly (7.7 (a) (i))

MOT #6 2018-12-13 12:00

**MOT test number** 982082448683

**Result** X Failed

**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure also sdewall separating (5.2.3 (d) (ii))

**Minor** Horn not working properly (7.7 (a) (i))

**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #5 2017-11-30 15:38

**MOT test number** 228409940868

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT test number

Result

Pass with rectification
Pass with rectification
Front registration plate deteriorated (6.3.1d)

Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #3 2016-12-15 10:11

MOT test number 668711846601

Result ✓ Passed

MOT #2 2016-06-22 13:56

MOT test number 932683741342

Result ✓ Passed

MOT #1 2015-12-21 15:24 MOT test number 806287220137

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 7/14



SB62YZR report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 May
Days left	367
MOT expiry date	10 February 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	59
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 8/14



report date: 2024-03-28

#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



faste since

SB62YZR

report date: 2024-03-28

More info >

# Owner history For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this TOYOTA had different number plates. about of pliates

CarCheck.co.uk page 11/14



SB62YZR report date: 2024-03-28

#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-12-24
Last registration	2024-02-09
Complete history	See info



Registration #1	2012-12-24	14 mi
Registration #2	2015-12-21	29.419 mi
Registration #3	2016-06-22	30.602 mi
Registration #4	2016-12-15	33.549 mi
Registration #5	2017-11-30	37.282 mi
Registration #6	2017-11-30	37.282 mi
Registration #7	2018-12-13	43.104 mi
Registration #8	2018-12-13	43.104 mi
Registration #9	2019-11-07	45.037 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91.777 es
Registration #16		11.777 es
Registration #17		10.707 au

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1760 mm
Height	1510 mm
Length	4245 mm
Wheel base	2600 mm
Kerb weight	1420 kg
Max. allowed weight	1805 kg

# Additional information

· · · · · · · · · · · · · · · · · · ·		
Fuel tank capacity	45 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pa	ge 14/14

Number of axles 2

**Engine number** 2ZRU511632