





report date: 2024-03-28

General information

Make	CITROEN
Model	C4 PICASSO BLUEHDI FLAIR S/S EAT6
Colour	Blue
Year of manufacture	2017
Top speed	117 mph
0 - 60 mph	11.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	65.7 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	103 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date 2022-04-30

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



GX67ZWA report date: 2024-03-28

MOT history

MOT expiry date	2024-06-15
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	19
Total items failed	0

MOT #6		2023-06-16 11:20
MOT test	number	251411660352
Result		✓ Passed
Next expi	ry date	2024-06-15
Advice Offside Front Tyre worn close to legal limit/worn on edge worn/bald edges (5.2.3 (e))		
Advice	Nearside Front Tyre worn close to legal limit/worn on edge bald edges (5.2.3 (e	2))

MOT #5		2023-06-16 10:50
MOT test	number	185034899555
Result		🗙 Failed
MAJOR	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice Offside Front Tyre worn close to legal limit/worn on edge worn/bald edges (5.2.3 (e))		(e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge bald edges (5.2.3 (e))

MOT #4	2022-06-16 15:54
MOT test number	535950230923
Result	✓ Passed
Advice Both front sill panels damaged	

CarCheck.co.uk page 3/11



MOT #1

Advice

GX67ZWA

report date: 2024-03-28

MOT #3 2021-06-07 10:46 **MOT** test number 642045056846 Result ✓ Passed **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #2 2020-09-04 15:26 **MOT** test number 249455606898 Result ✓ Passed Advice Nearside Rear Tyre slightly damaged/cracking or perishing Tyre perishing. (5.2.3 (d) (ii)) **Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing Tyre perishing. (5.2.3 (d) (ii)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge Tyre worn on outer edge. (5.2.3 (e))

2020-09-04 14:34 **MOT** test number 282227248995 Result × Failed **MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i)) Offside Front Tyre worn close to legal limit/worn on edge Tyre worn on outer edge. (5.2.3 (e)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing Tyre perishing. (5.2.3 (d) (ii)) Advice **Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Nearside Front Tyre worn close to legal limit/worn on edge Tyre worn on outer edge. (5.2.3 (e)) **Advice**

Nearside Rear Tyre slightly damaged/cracking or perishing Tyre perishing. (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



GX67ZWA report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	15 June 2024
Full MOT history	See MOT history

Tax calculation

-	
Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

_	
Owner	history
OWITCE	ilistoi y

For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-09-25
Last registration	2023-06-16
Complete history	See info



Registration #1	2017-09-25	24 mi
Registration #2	2020-09-04	25.191 mi
Registration #3	2020-09-04	25.192 mi
Registration #4	2021-06-07	27.433 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



GX67ZWA report date: 2024-03-28

Safety ratings

NCAP rating

Video <u>see crash video</u>

Dimensions & weight

Width	1826 mm
Height	1625 mm
Length	4428 mm
Wheel base	2785 mm
Kerb weight	1320 kg
Max. allowed weight	1975 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBHD3073961

CarCheck.co.uk page 11/11