



PEUGEOT



SB60VDL


report date: 2024-03-29

General information

Make	PEUGEOT
Model	107 URBAN LITE
Colour	Blue
Year of manufacture	2011
Top speed	98 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	52.3 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	103 g/km
CO2 label	B





Internet history

Entry 2

Date	2021-06-22
Pictures	3
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-13
Pictures	3
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-06-26
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	19
Total items failed	3

MOT #14	2023-06-14 14:45
MOT test number	123754837000
Result	✓ Passed
Next expiry date	2024-06-26
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #13	2023-06-14 10:57
MOT test number	686004704391
Result	✗ Failed
Fail	Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #12**

2022-06-15 10:35

**MOT test number**

108130035546

**Result**

✓ Passed

**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #11**

2021-06-27 15:01

**MOT test number**

569785550198

**Result**

✓ Passed

**MOT #10**

2020-07-20 08:55

**MOT test number**

836024714700

**Result**

✓ Passed

**Advice** Brake pipe corroded, covered in grease or other material all (1.1.11 (c))**Advice** Exhaust condition**Advice** Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))**Advice** Offside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))**Advice** Front crossmember corroded**MOT #9**

2019-07-30 11:02

**MOT test number**

403348963482

**Result**

✓ Passed

**Advice** Offside Brake pipe corroded, covered in grease or other material main front to rear at rear (1.1.11 (c))**Advice** Nearside Brake pipe corroded, covered in grease or other material main front to rear at rear (1.1.11 (c))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #8** 2018-07-18 11:50**MOT test number** 123285401277**Result** ✓ Passed**Advice** Advise some corrosion on brake pipes**MOT #7** 2017-07-21 08:39**MOT test number** 811078809736**Result** ✓ Passed**MOT #6** 2016-06-20 10:53**MOT test number** 555658038865**Result** ✓ Passed**MOT #5** 2015-06-24 12:23**MOT test number** 386915175199**Result** ✓ Passed**MOT #4** 2015-06-24 12:23**MOT test number** 725545375122**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**MOT #3** 2015-01-26 13:47**MOT test number** 956836325010**Result** ✓ Passed**MOT #2** 2014-02-04 14:24**MOT test number** 527215034032**Result** ✓ Passed



MOT #1	2014-02-01 10:20
MOT test number	946892434010
Result	✗ Failed
Fail	Nearside Rear Shock absorber has a serious fluid leak (2.7.3)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
26 June 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	62
<b>MOT expiry date</b>	26 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-01-31
Last registration	2023-06-14
Complete history	<a href="#">See info</a>



Registration #1	2011-01-31	9 mi
Registration #2	2014-02-01	20.873 mi
Registration #3	2014-02-04	20.875 mi
Registration #4	2015-01-26	27.195 mi
Registration #5	2015-06-24	28.178 mi
Registration #6	2016-06-20	29.932 mi
Registration #7	2017-07-21	31.746 mi
Registration #8	2018-07-18	33.194 mi
Registration #9	2019-06-20	35.277 mi
Registration #10	2020-06-20	37.360 mi
Registration #11	2021-06-20	39.443 mi
Registration #12	2022-06-20	41.526 mi
Registration #13	2023-06-14	43.609 mi
Registration #14	2024-03-29	45.692 mi
Registration #15	2024-03-29	47.775 mi
Registration #16	2024-03-29	49.858 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	7010031