



report date: 2024-03-28

General information

Make	KIA
Model	CEED PRO CEED STRIKE
Colour	Blue
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	137 Nm at 5.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	48.7 mpg



LABEL UNKNOWN



Internet history

Entry 1	
Date	2021-06-12
Pictures	12
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history****MOT #14** 2022-02-11 11:50**MOT test number** 611030577934**Result** ✗ Failed**Fail** Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))**Fail** Windscreen washer not working (3.5 (a))**Fail** Exhaust hydrocarbon content after 2nd fast idle exceeds default limits (8.2.1.2 (b))**Fail** Offside Rear Direction indicator not working (4.4.1 (a) (ii))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #13** 2021-01-08 15:44**MOT test number** 705833441256**Result** ✓ Passed**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Surface corrosion to under floor components**MOT #12** 2020-01-27 11:38**MOT test number** 552253651488**Result** ✓ Passed**Advice** Rear discs slight surface corrosion**MOT #11** 2020-01-27 11:38**MOT test number** 620337045129**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Rear discs slight surface corrosion

**MOT #10** 2019-02-28 14:08**MOT test number** 537502423245**Result** ✓ Passed**MOT #9** 2019-02-28 14:08**MOT test number** 573615645235**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii))**MOT #8** 2018-02-26 10:12**MOT test number** 367214583430**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2018-02-26 08:42**MOT test number** 802446850423**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)

**MOT #6** 2017-02-09 15:07**MOT test number** 414910935947**Result** ✓ Passed**MOT #5** 2016-02-26 12:27**MOT test number** 310840834665**Result** ✓ Passed**MOT #4** 2016-02-26 12:27**MOT test number** 904712843255**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively both (8.2.2)**MOT #3** 2015-02-27 14:19**MOT test number** 236458155007**Result** ✓ Passed**Notice** Front discs worn**Notice** Rear tyres cracking**MOT #2** 2014-05-23 11:58**MOT test number** 605023944160**Result** ✓ Passed**Notice** Rear discs worn**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2013-05-29 13:05**MOT test number** 686079543196**Result** ✓ Passed



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	<b>FP10BMV</b>
Plate since	2019-09-28
Current registration	<b>FP10BMV</b>
Plate since	2019-09-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-04-19
Last registration	2022-02-11
Complete history	<a href="#">See info</a>



Registration #1	2010-04-19	15 mi
Registration #2	2013-05-29	38.007 mi
Registration #3	2014-05-23	42.450 mi
Registration #4	2015-02-27	46.759 mi
Registration #5	2016-02-26	56.763 mi
Registration #6	2016-02-26	56.763 mi
Registration #7	2017-02-09	78.044 mi
Registration #8	2018-02-26	97.211 mi
Registration #9	2019-05-29	115.217 mi
Registration #10	2019-05-29	115.217 mi
Registration #11	2019-05-29	115.217 mi
Registration #12	2019-05-29	115.217 mi
Registration #13	2019-05-29	115.217 mi
Registration #14	2019-05-29	115.217 mi
Registration #15	2019-05-29	115.217 mi
Registration #16	2022-02-11	115.217 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1790 mm
Height	1450 mm
Length	4250 mm
Wheel base	2650 mm
Kerb weight	1257 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	G4FA9Z201257