




report date: 2024-03-29

General information

Make	CITROEN
Model	GRAND C4 PICASSO HDI VTR PLUS GRAND PICASSO
Colour	Purple
Year of manufacture	2009
Top speed	112 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.9 mpg
CO2 emission	145 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-10-28
Pictures	12
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-12-07
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	40
Total items failed	12

MOT #19	2023-12-08 16:00
MOT test number	549872059854
Result	✓ Passed
Next expiry date	2024-12-07
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #18	2022-11-22 13:41
MOT test number	484332484833
Result	✓ Passed

MOT #17	2021-11-08 16:03
MOT test number	861157292108
Result	✓ Passed
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16**

2020-11-18 13:06

**MOT test number**

738496556874

**Result**

✓ Passed

**Advice** Offside Rear Nail in tyre**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge and perishing (5.2.3 (e))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge and perishing (5.2.3 (e))**MOT #15**

2020-11-13 11:19

**MOT test number**

758978463719

**Result**

✗ Failed

**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge and perishing (5.2.3 (e))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Rear Nail in tyre**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge and perishing (5.2.3 (e))**MOT #14**

2019-11-25 11:17

**MOT test number**

489596580934

**Result**

✓ Passed

**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #13**

2019-11-23 10:27

**MOT test number**

534455788496

**Result****✗ Failed**

- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #12**

2018-11-28 12:34

**MOT test number**

691528239979

**Result****✓ Passed**

- Minor** Front Windscreen wiper blade defective both (3.4 (b) (i))
- Advice** Rear Direction indicator slightly discoloured both (4.4.3 (a))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #11**

2018-11-23 10:08

**MOT test number**

609759313681

**Result****✗ Failed**

- Minor** Front Windscreen wiper blade defective both (3.4 (b) (i))
- Advice** Rear Direction indicator slightly discoloured both (4.4.3 (a))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

**MOT #10** 2017-11-24 14:08**MOT test number** 890224611997**Result** ✓ Passed**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**MOT #9** 2017-11-21 10:07**MOT test number** 202534197847**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #8** 2016-11-23 11:18**MOT test number** 451835824091**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt 2 rear**MOT #7** 2015-11-19 13:41**MOT test number** 740492279844**Result** ✓ Passed**Advice** Unable to check 3rd row seats.**Advice** EML on

**MOT #6** 2015-11-19 11:16**MOT test number** 640142827338**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Unable to check 3rd row seats.**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** EML on**MOT #5** 2014-11-21 14:50**MOT test number** 685235124349**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Oil leak**MOT #4** 2013-11-22 17:09**MOT test number** 355836623391**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #3** 2013-11-22 12:46**MOT test number** 488426823416**Result** ✗ Failed**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



MOT #2	2012-11-07 09:55
MOT test number	959732912335
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2012-11-07 09:55
MOT test number	998892912360
Result	✗ Failed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Nearside Front Front position lamp(s) not working (1.1.A.3b)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
7 December 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	186
<b>MOT expiry date</b>	7 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-11-23
Last registration	2023-12-08
Complete history	<a href="#">See info</a>



Registration #1	2009-11-23	18 mi
Registration #2	2012-11-07	16.991 mi
Registration #3	2013-11-22	26.359 mi
Registration #4	2013-11-22	26.407 mi
Registration #5	2014-11-21	38.434 mi
Registration #6	2015-11-19	48.088 mi
Registration #7	2015-11-19	48.088 mi
Registration #8	2016-11-23	57.136 mi
Registration #9	2017-11-21	68.053 mi
Registration #10	2017-11-24	68.140 mi
Registration #11	2018-11-21	78.177 mi
Registration #12	2019-11-20	88.214 mi
Registration #13	2020-11-19	98.251 mi
Registration #14	2021-11-18	108.288 mi
Registration #15	2022-11-17	118.325 mi
Registration #16	2023-11-16	128.362 mi
Registration #17	2024-11-15	138.399 mi
Registration #18	2025-11-14	148.436 mi
Registration #19	2026-11-13	158.473 mi
Registration #20	2027-11-12	168.510 mi

More info >



Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)

Dimensions & weight

Width	1829 mm
Height	1700 mm
Length	4585 mm
Wheel base	2728 mm
Kerb weight	1530 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBCV0048476