



report date: 2024-03-29

General information

| | |
|---------------------|-------------------|
| Make | VOLVO |
| Model | V70 D3 SE NAV |
| Colour | Silver |
| Year of manufacture | 2015 |
| Top speed | 127 mph |
| 0 - 60 mph | 9.2 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 148 BHP |
| Max. torque | 320 Nm at 1.750 rpm |
| Engine capacity | 1.969 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 56.5 mpg |
| Consumption extra urban | 67.3 mpg |
| Consumption combined | 62.8 mpg |
| CO2 emission | 118 g/km |
| CO2 label | C |





Internet history

Entry 4

| | |
|---------------|-----------------------------|
| Date | 2021-07-10 |
| Pictures | 26 |
| Listing price | View report |



source: [autotrader.co.uk](#)

Entry 3

| | |
|---------------|-----------------------------|
| Date | 2021-06-25 |
| Pictures | 26 |
| Listing price | View report |



source: [autotrader.co.uk](#)

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2021-06-12 |
| Pictures | 26 |
| Listing price | View report |



source: [autotrader.co.uk](#)

Entry 1

| | |
|------|------------|
| Date | 2021-05-26 |
|------|------------|

Pictures

22

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-04-19 |
| MOT pass rate | 67 % |
| MOT passed | 6 |
| Failed MOT tests | 3 |
| Total advice items | 13 |
| Total items failed | 7 |

| | |
|------------------|---|
| MOT #9 | 2024-04-02 14:38 |
| MOT test number | 788386567572 |
| Result | ✓ Passed |
| Next expiry date | 2025-04-19 |
| Minor | Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) |

| | |
|-----------------|--|
| MOT #8 | 2023-04-07 09:55 |
| MOT test number | 327147142319 |
| Result | ✓ Passed |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Nearside Front headlight lens cracked |
| Advice | Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|-----------------|------------------|
| MOT #7 | 2022-04-01 14:52 |
| MOT test number | 356829308679 |
| Result | ✓ Passed |

**MOT #6**

2022-04-01 09:04

MOT test number

540844205073

Result**✗ Failed****Fail** Rear Brake disc significantly and obviously worn both sides (1.1.14 (a) (i))**Fail** Rear Brake pad(s) less than 1.5 mm thick both sides (1.1.13 (a) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #5**

2021-04-20 15:17

MOT test number

877035176763

Result**✓ Passed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Outer Brake disc worn, but not excessively both (1.1.14 (a) (i))**Advice** Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**MOT #4**

2021-04-13 16:35

MOT test number

771898023335

Result**✗ Failed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Rear Outer Brake disc worn, but not excessively both (1.1.14 (a) (i))



MOT #3 2020-05-27 11:19

MOT test number 447405751012

Result ✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear tyres getting low on inside edges

MOT #2 2018-07-16 14:34

MOT test number 910983871341

Result ✓ Passed

MOT #1 2018-07-12 15:32

MOT test number 224948044308

Result ✗ Failed

Fail Offside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
19 April 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 November |
| Days left | 186 |
| MOT expiry date | 19 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 49 |
| Band | C |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 15,200 |
| Auction value | £ 15,200 |
| Average private trade value | £ 15,200 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------|
| Owner | Period |
| Owner | Period |
| Owner | Period |
| Owner | Period |
| Owner | Period |
| Owner | Period |
| Owner | Period |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | YW15GZT |
| Plate since | 2015-06-29 |
| Current registration | YW15GZT |
| Plate since | 2015-06-29 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 14 |
| First mileage registration | 2015-07-31 |
| Last registration | 2024-04-02 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2015-07-31 | 12 mi |
| Registration #2 | 2018-07-12 | 147.762 mi |
| Registration #3 | 2018-07-16 | 147.762 mi |
| Registration #4 | 2020-05-27 | 152.536 mi |
| Registration #5 | 2021-04-13 | 153.541 mi |
| Registration #6 | 2021-04-20 | 153.549 mi |
| Registration #7 | 2022-05-20 | 153.557 mi |
| Registration #8 | 2022-05-20 | 153.557 mi |
| Registration #9 | 2022-05-20 | 153.557 mi |
| Registration #10 | 2022-05-20 | 153.557 mi |
| Registration #11 | 2022-05-20 | 153.557 mi |
| Registration #12 | 2022-05-20 | 153.557 mi |
| Registration #13 | 2022-05-20 | 153.557 mi |
| Registration #14 | 2022-05-20 | 153.557 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 88% |
| Children | 84% |
| Pedestrian | 43% |
| Safety systems | 71% |
| Overall rating | 77% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2106 mm |
| Height | 1547 mm |
| Length | 4814 mm |
| Wheel base | 2816 mm |
| Kerb weight | 1738 kg |
| Max. allowed weight | 2290 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 70 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|---------|
| Number of axles | 2 |
| Engine number | 1317346 |