



report date: 2024-03-29

General information

Make	CITROEN
Model	C2 LOEB
Colour	Grey
Year of manufacture	2007
Top speed	126 mph
0 - 60 mph	8.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	143 Nm at 3.750 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	163 g/km
CO2 label	G







Internet history

Entry 1

Date	2021-10-14
Pictures	29
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-10-16
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	10
Total items failed	19

MOT #18	2023-10-17 11:30
MOT test number	958373521104
Result	✓ Passed
Next expiry date	2024-10-16

MOT #17	2022-10-13 09:11
MOT test number	999462422201
Result	✓ Passed
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Advice	Offside Rear Integral body structure is repaired but structural rigidity is not significantly reduced (6.1.1 (d) (i))

MOT #16	2021-10-07 13:31
MOT test number	584457618657
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Both floors, chassis rails, under sills, outer sills and inner flitches slightly corroded

**MOT #15** 2021-10-05 11:38**MOT test number** 886474962352**Result** ✗ Failed**Advice** Both floors, chassis rails, under sills, outer sills and inner flitches slightly corroded**Fail** Exhaust noise is clearly in excess of that emitted by a similar vehicle fitted with a standard silencer in average condition (8.1.1 (a))**Fail** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))**Fail** Exhaust has a major leak of exhaust gases rear joint (6.1.2 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**MOT #14** 2020-09-23 08:25**MOT test number** 856286988165**Result** ✓ Passed**MOT #13** 2020-09-22 08:43**MOT test number** 857736113216**Result** ✗ Failed**Fail** Offside Front Service brake excessively fluctuating (1.2.1 (e))**Fail** Front Exhaust has a major leak of exhaust gases CATALYST REAR FLANGE. (6.1.2 (a))**MOT #12** 2019-04-15 08:55**MOT test number** 406999605884**Result** ✓ Passed**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2019-04-15 08:55**MOT test number** 143416608469**Result** ✗ Failed

**Pass with rectification** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

**MOT #10** 2018-04-16 13:50**MOT test number** 478695036990**Result** ✓ Passed

**Advice** Oil leak

**MOT #9** 2018-04-10 13:02**MOT test number** 614159598949**Result** ✗ Failed

**Fail** Offside Stop lamp not working (1.2.1b)

**Fail** Nearside Front Anti-roll bar linkage has excessive play in a pin/bush loose no bolt (2.4.G.2)

**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**Advice** Oil leak

**Fail** Nearside Registration plate lamp not working (1.1.C.1d)

**Fail** Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)

**Fail** Offside Rear position lamp(s) not working (1.1.A.3b)

**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)

**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)

**Fail** Front Brakes imbalanced across an axle Axle 1 (3.7.B.5b)



<b>MOT #8</b>	2015-09-19 14:10
---------------	------------------

<b>MOT test number</b>	317283133115
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #7</b>	2014-09-30 13:23
---------------	------------------

<b>MOT test number</b>	567563774204
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #6</b>	2013-09-03 12:56
---------------	------------------

<b>MOT test number</b>	347326443226
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2012-09-25 10:41
---------------	------------------

<b>MOT test number</b>	345679262473
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2012-09-25 10:41
---------------	------------------

<b>MOT test number</b>	466649562220
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Pass with rectification</b>	Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
--------------------------------	---

<b>MOT #3</b>	2011-09-06 09:15
---------------	------------------

<b>MOT test number</b>	366489541211
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2010-09-16 11:17
---------------	------------------

<b>MOT test number</b>	592279250285
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



MOT #1	2010-03-04 16:13
MOT test number	583543560034
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
16 October 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	16 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-03-23
Last registration	2023-10-17
Complete history	<a href="#">See info</a>



Registration #1	2007-03-23	17 mi
Registration #2	2010-03-04	22.801 mi
Registration #3	2010-09-16	26.678 mi
Registration #4	2011-09-06	37.641 mi
Registration #5	2012-09-25	47.049 mi
Registration #6	2013-09-03	57.860 mi
Registration #7	2014-09-30	72.194 mi
Registration #8	2015-09-19	81.946 mi
Registration #9	2018-04-10	82.469 mi
Registration #10	2018-04-16	82.469 mi
Registration #11	2019-05-20	85.377 mi
Registration #12	2019-05-20	85.377 mi
Registration #13	2019-05-20	85.377 mi
Registration #14	2019-05-20	85.377 mi
Registration #15	2019-05-20	85.377 mi
Registration #16	2019-05-20	85.377 mi
Registration #17	2019-05-20	85.377 mi
Registration #18	2019-05-20	85.377 mi
Registration #19	2019-05-20	85.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1659 mm
Height	1474 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	1083 kg
Max. allowed weight	1415 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FX6C3201682