



report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA DESIRE 16V PICASSO E4
Colour	Grey
Year of manufacture	2006
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-07-11
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-24
MOT pass rate	70 %
MOT passed	16
Failed MOT tests	7
Total advice items	60
Total items failed	5

MOT #23	2024-04-25 16:01
---------	------------------

MOT test number	907628373076
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-04-24
------------------	------------

- Advice** Central exhaust badly corroded
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing splits in tread (5.2.3 (d) (ii))
- Advice** Reg light unit loose / insecure
- Advice** Offside Front Tyre slightly damaged/cracking or perishing splits in tread (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing splits in tread (5.2.3 (d) (ii))
- Advice** Boot lock faulty
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #22**

2024-04-17 13:51

MOT test number

395035836044

Result**✗ Failed****MAJOR** Rear Exhaust has a major leak of exhaust gases box fractured (6.1.2 (a))**Advice** Reg light unit loose / insecure**MAJOR** Emissions unable to be completed due to condition of exhaust system (8.2.1.2 (d))**Advice** Offside Front Tyre slightly damaged/cracking or perishing splits in tread (5.2.3 (d) (ii))**Advice** Central exhaust badly corroded**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing splits in tread (5.2.3 (d) (ii))**MAJOR** Nearside Headlamp aim projected beam image is obviously incorrect bulb incorrectly fitted / faulty (4.1.2 (c))**MAJOR** Offside Front Suspension arm pin or bush excessively worn wishbone rear support (5.3.4 (a) (i))**MAJOR** Offside Inner Steering rack has excessive free play detected at the steering wheel (steering rack fitted) steering knuckle badly worn (2.3 (a) (i))**Advice** Boot lock faulty**DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Front discs badly worn / lipped**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing splits in tread (5.2.3 (d) (ii))**Advice** Front Brake pad(s) wearing thin very thin (1.1.13 (a) (ii))**MAJOR** Nearside Front Suspension arm pin or bush excessively worn wishbone rear support (5.3.4 (a) (i))

**MOT #21** 2023-07-13 15:34**MOT test number** 553506428194**Result** ✓ Passed**Advice** No access to boot**Advice** Nearside Front Tyre worn close to legal limit/worn on edge also perished (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #20** 2022-06-29 09:13**MOT test number** 189364272994**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front discs worn**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Central exhaust box deteriorated**MOT #19** 2021-07-13 12:45**MOT test number** 678989821172**Result** ✓ Passed**Advice** Offside Front Play in steering rack inner joint(s)

**MOT #18**

2021-07-12 16:15

MOT test number

460298901210

Result**✗ Failed****Advice** Nearside Rear Nail in tyre**Advice** Offside Front Play in steering rack inner joint(s)**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Nearside Outer Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))**DANGEROUS** Offside Rear Passenger's seat insecure (6.2.6 (a) (ii))**MOT #17**

2020-08-24 08:22

MOT test number

418554263633

Result**✓ Passed****Advice** Offside Front Suspension component mounting repair covered in underseal outer sill (5.3.6 (a) (i))**Advice** Nearside Outer Seat belt anchorage prescribed area is corroded but not considered excessive sill (7.1.1 (a) (i))**MOT #16**

2020-08-21 12:33

MOT test number

261964505303

Result**✗ Failed****MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Outer Seat belt anchorage prescribed area is corroded but not considered excessive sill (7.1.1 (a) (i))**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Offside Outer Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))**MAJOR** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

**MOT #15** 2019-08-17 14:19**MOT test number** 905417980829**Result** ✓ Passed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement "P"
Bush (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #14** 2018-09-20 08:16**MOT test number** 823099765256**Result** ✓ Passed**Advice** N/s/f lower arm (rear bush) deteriorated.**MOT #13** 2018-09-20 08:16**MOT test number** 624535633452**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))**Advice** N/s/f lower arm (rear bush) deteriorated.**MOT #12** 2017-09-19 09:45**MOT test number** 311662175075**Result** ✓ Passed**Advice** Rear exhaust bracket broken**Advice** Exhaust system corroded

**MOT #11** 2016-09-20 09:48**MOT test number** 450920952158**Result** ✓ Passed

- Advice** Nearside front wheel buckled slightly on inner edge
- Advice** Both front lower arm rear rubber bushes becoming slightly perished
- Advice** Rear view mirror becoming delaminated
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Both rear tyres becoming perished on inner sidewalls

MOT #10 2015-09-21 08:56**MOT test number** 614151367170**Result** ✓ Passed

- Advice** Parking brake travel slightly excessive

MOT #9 2015-09-21 08:56**MOT test number** 863248001226**Result** ✗ Failed

- Pass with rectification** Offside Stop lamp not working (1.2.1b)
- Advice** Parking brake travel slightly excessive

MOT #8 2014-09-19 14:20**MOT test number** 869282664227**Result** ✓ Passed

- Notice** Offside front tyre 3mm tread and wearing on the inner edge.
- Notice** Middle exhaust slightly corroded.

**MOT #7** 2013-09-24 12:27**MOT test number** 205187663291**Result** ✓ Passed**MOT #6** 2012-10-09 12:34**MOT test number** 258093482247**Result** ✓ Passed**Notice** Both rear tyres 2.5mm and perrished**MOT #5** 2011-09-29 10:02**MOT test number** 628392571265**Result** ✓ Passed**MOT #4** 2010-10-19 17:21**MOT test number** 912072190238**Result** ✓ Passed**MOT #3** 2010-10-19 17:21**MOT test number** 850292790204**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too low (1.8)**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**MOT #2** 2009-11-30 16:44**MOT test number** 754714339317**Result** ✓ Passed



MOT #1	2009-11-30 14:49
MOT test number	360514839377
Result	✗ Failed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
24 April 2025

Tax status	Valid until 1 July
Days left	62
MOT expiry date	24 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	HW56GRZ
Plate since	2019-09-29
Current registration	HW56GRZ
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-12-20
Last registration	2024-04-25
Complete history	See info



Registration #1	2006-12-20	18 mi
Registration #2	2009-11-30	26.655 mi
Registration #3	2009-11-30	26.656 mi
Registration #4	2010-10-19	29.678 mi
Registration #5	2011-09-29	35.265 mi
Registration #6	2012-10-09	40.371 mi
Registration #7	2013-09-24	45.668 mi
Registration #8	2014-09-19	50.989 mi
Registration #9	2015-09-21	56.028 mi
Registration #10	2015-09-21	56.028 mi
Registration #11	2016-09-20	61.055 mi
Registration #12	2017-09-19	65.177 mi
Registration #13	2018-09-19	69.299 mi
Registration #14	2019-09-19	73.421 mi
Registration #15	2020-09-19	77.543 mi
Registration #16	2021-09-19	81.665 mi
Registration #17	2022-09-19	85.787 mi
Registration #18	2023-09-19	89.909 mi
Registration #19	2024-04-25	94.031 mi
Registration #20	2024-04-25	94.031 mi
Registration #21	2024-04-25	94.031 mi
Registration #22	2024-04-25	94.031 mi
Registration #23	2024-04-25	94.031 mi
Registration #24	2024-04-25	94.031 mi

More info >



Safety ratings

NCAP rating

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1240 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX6P3098348