



report date: 2024-03-28

General information

|                     |                    |
|---------------------|--------------------|
| Make                | VOLVO              |
| Model               | V50 D DRIVE SE LUX |
| Colour              | Silver             |
| Year of manufacture | 2011               |
| Top speed           | 118 mph            |
| 0 - 60 mph          | 10.9 seconds       |
| Gearbox             | 5 speed Manual     |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 109 BHP             |
| Max. torque             | 240 Nm at 1.750 rpm |
| Engine capacity         | 1.560 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 57.7 mpg            |
| Consumption extra urban | 83.1 mpg            |
| Consumption combined    | 72.4 mpg            |
| CO2 emission            | 99 g/km             |
| CO2 label               | A                   |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-06-25                  |
| Pictures      | 0                           |
| Listing price | <a href="#">View report</a> |

source: cargurus.co.uk



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2022-10-22 |
| MOT pass rate      | 89 %       |
| MOT passed         | 8          |
| Failed MOT tests   | 1          |
| Total advice items | 8          |
| Total items failed | 3          |

MOT #9 2021-10-23 10:06

MOT test number 799526438166

Result ✓ Passed

Next expiry date 2022-10-22

**Advice** Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords wall (5.2.3 (d) (i))

**Advice** Engine and under covers fitted obscuring some components

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #8 2021-10-20 16:11

MOT test number 653602409665

Result ✗ Failed

**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))

**Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords wall (5.2.3 (d) (i))

**MOT #7** 2020-12-19 09:09**MOT test number** 492936549979**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #6** 2019-11-29 17:28**MOT test number** 299558685605**Result** ✓ Passed**MOT #5** 2018-11-23 10:58**MOT test number** 470903928080**Result** ✓ Passed**MOT #4** 2017-11-15 10:37**MOT test number** 601941598553**Result** ✓ Passed**MOT #3** 2016-11-28 11:45**MOT test number** 649164996617**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2015-11-14 09:24**MOT test number** 256863676568**Result** ✓ Passed**MOT #1** 2014-11-15 13:32**MOT test number** 925169014348**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
8 May 2021

X

MOT

Expired:  
22 October 2022

|                  |                                 |
|------------------|---------------------------------|
| Tax status       | Expired at 8 May 2021           |
| Days left        | 1086 days too late              |
| MOT expiry date  | 22 October 2022                 |
| Full MOT history | <a href="#">See MOT history</a> |

Tax calculation

|   |                |
|---|----------------|
| Vehicle class                           | 49             |
| Band                                    | A              |
| Single payment (12 months)              | £ 0,00,-       |
| Single six month payment                | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |        |
|-------|--------|
| Owner | Period |
| Owner | Period |
| Owner | Period |
| Owner | Period |
| Owner | Period |
| Owner | Period |
| Owner | Period |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

|                      |                |
|----------------------|----------------|
| Number of plates     | 1              |
| Current registration | <b>RV61DXP</b> |
| Plate since          | 2024-03-28     |
| Current registration | <b>RV61DXP</b> |
| Plate since          | 2024-03-28     |

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 11                       |
| First mileage registration | 2011-11-17               |
| Last registration          | 2021-10-23               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2011-11-17 | 12 mi     |
| Registration #2  | 2014-11-15 | 23.256 mi |
| Registration #3  | 2015-11-14 | 27.956 mi |
| Registration #4  | 2016-11-28 | 33.517 mi |
| Registration #5  | 2017-11-15 | 38.897 mi |
| Registration #6  | 2018-11-23 | 43.049 mi |
| Registration #7  | 2019-10-20 | 45.277 mi |
| Registration #8  | 2020-05-20 | 45.277 mi |
| Registration #9  | 2020-05-20 | 45.277 mi |
| Registration #10 | 2020-05-20 | 45.277 mi |
| Registration #11 | 2021-10-23 | 45.277 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 91%                             |
| Children       | 78%                             |
| Pedestrian     | 26%                             |
| Safety systems | 71%                             |
| Overall rating | 73%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1770 mm |
| Height              | 1457 mm |
| Length              | 4522 mm |
| Wheel base          | 2640 mm |
| Kerb weight         | 1437 kg |
| Max. allowed weight | 1900 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 52 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 5                |

|                 |         |
|-----------------|---------|
| Number of axles | 2       |
| Engine number   | 1760212 |