



report date: 2024-03-29

General information

Make	SUZUKI
Model	SWIFT SPORT
Colour	Black
Year of manufacture	2013
Top speed	121 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	160 Nm at 4.400 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.1 mpg
CO2 emission	147 g/km
CO2 label	F





## Internet history

### Entry 7

Date 2021-09-17

Pictures 10

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 6

Date 2021-09-03

Pictures 10

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 5

Date 2021-08-05

Pictures 10

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 4

Date 2021-07-17

CarCheck.co.uk

Pictures

10

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 3

Date

2021-07-02

Pictures

10

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 2

Date

2021-06-11

Pictures

10

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 1

Date

2021-05-21

Pictures

10

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-05-07
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	35
Total items failed	17

MOT #13	2023-05-05 12:50
MOT test number	407659121274
Result	✓ Passed
Next expiry date	2024-05-07
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2023-05-03 10:26
MOT test number	620157505315
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Offside Rear Brake pipe excessively corroded (1.1.11 (c))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
Fail	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11**

2022-05-04 12:48

**MOT test number**

266139585865

**Result**

✓ Passed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #10**

2022-05-04 12:06

**MOT test number**

244665006199

**Result**

✗ Failed

- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #9**

2021-05-08 08:24

**MOT test number**

220517523935

**Result**

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both front brake discs (1.1.14 (a) (ii))



<b>MOT #8</b>	2020-10-02 09:07
<b>MOT test number</b>	452036398097
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Offside Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #7</b>	2020-09-24 13:28
<b>MOT test number</b>	277703102683
<b>Result</b>	✗ Failed
<b>Advice</b>	Offside Rear Service brake binding but not excessively (1.2.1 (f))
<b>Fail</b>	Windscreen washer not working (3.5 (a))
<b>Advice</b>	Nearside Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Fail</b>	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
<b>Advice</b>	Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
<b>Fail</b>	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
<b>Fail</b>	Brake lever has insufficient reserve travel (1.1.2 (a))
<b>Fail</b>	Nearside Front Position lamp not working (4.2.1 (a) (ii))
<b>Advice</b>	Offside Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Fail</b>	Offside Stop lamp(s) not working (4.3.1 (a) (ii))

<b>MOT #6</b>	2019-09-26 11:12
<b>MOT test number</b>	560149890260
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
<b>Advice</b>	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



**MOT #5** 2019-09-25 15:20**MOT test number** 500484654190**Result** ✗ Failed**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Offside Rear Brake performance not tested Pads on metal (1.2.1 (g))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #4** 2018-09-17 14:22**MOT test number** 204769234869**Result** ✓ Passed**Minor** Front Windscreen wiper blade defective (3.4 (b) (i))**MOT #3** 2017-09-06 10:43**MOT test number** 188241162942**Result** ✓ Passed**MOT #2** 2017-06-21 09:43**MOT test number** 567627162569**Result** ✓ Passed





MOT #1	2016-06-25 14:19
MOT test number	532285395815
Result	✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Brake pad(s) wearing thin (3.5.1g)
Advice	Parking brake lever has little reserve travel (3.1.6b)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
7 May 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	7 May 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2013-06-07
Last registration	2023-05-05
Complete history	<a href="#">See info</a>



Registration #1	2013-06-07	28 mi
Registration #2	2016-06-25	38.165 mi
Registration #3	2017-06-21	53.000 mi
Registration #4	2017-09-06	53.010 mi
Registration #5	2018-09-17	75.079 mi
Registration #6	2019-09-25	86.251 mi
Registration #7	2019-09-26	86.255 mi
Registration #8	2020-09-24	97.919 mi
Registration #9	2020-10-02	98.232 mi
Registration #10	2021-05-08	104.953 mi
Registration #11	2022-05-20	121.277 mi
Registration #12	2022-05-20	121.277 mi
Registration #13	2022-05-20	121.277 mi
Registration #14	2022-05-20	121.277 mi
Registration #15	2022-05-20	121.277 mi
Registration #16	2022-05-20	121.277 mi
Registration #17	2022-05-20	121.277 mi
Registration #18	2022-05-20	121.277 mi
Registration #19	2022-05-20	121.277 mi
Registration #20	2022-05-20	121.277 mi
Registration #21	2022-05-20	121.277 mi

More info >





Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	62%
Safety systems	71%
Overall rating	83%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1695 mm
Height	1510 mm
Length	3890 mm
Wheel base	2430 mm
Max. allowed weight	1480 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	M16A-1745666