





report date: 2024-03-28

General information

Make	PEUGEOT
Model	207 HDI SW ALLURE
Colour	Red
Year of manufacture	2011
Top speed	113 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	67.3 mpg
CO2 emission	110 g/km
CO2 label	В



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-07-10

Pictures 25

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-08-29
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	17
Total items failed	7

MOT #14	2023-08-30 13:32
MOT test number	461145453726
Result	✓ Passed
Next expiry date	2024-08-29
Advice Lower Gearbox mounting defective	
Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice Rear Sound deadening material not fully secure Exhaust (8.1.1 (b) (i))	

MOT #13		2022-08-30 13:29
MOT test	number	989246564245
Result		✓ Passed
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))	
Advice	Both sides hand brake efficiency poor	

CarCheck.co.uk page 3/13



MOT #12 2022-08-24 14:34

MOT test number 478351845739

Result X Failed

Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Both sides hand brake efficiency poor

Fail Brake lever has insufficient reserve travel (1.1.2 (a))

Advice Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MOT #11 2021-08-24 18:08

MOT test number 674428786390

MOT #10 2021-08-24 18:08

MOT test number 498629586818

Result X Failed

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b)

(ii))

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #9 2021-02-08 10:37

MOT test number 504603329703

Result \square Passed

MOT #8 2020-02-05 16:18

MOT test number 698786950891

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

CarCheck.co.uk page 4/13



MOT #7 2020-01-30 12:47

MOT test number 256319254474

Result X Failed

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Fail Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))

MOT #6 2019-02-08 11:57

MOT test number 267034682567

Result ✓ Passed

MOT #5 2018-05-21 14:34

MOT test number 497251997702

Result Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2017-05-15 08:27

MOT test number 860110255154

Result

Passed

Advice Nearside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)

MOT #3 2016-05-16 09:24

MOT test number 767122772788

Result
✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 5/13



 MOT #2
 2015-05-11 16:49

 MOT test number
 196661235119

 Result
 ✓ Passed

 MOT #1
 2014-05-19 11:23

 MOT test number
 739509834194

 Result
 ✓ Passed

 Advice
 Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	29 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e when miscory	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full in	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	NK SIN
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-05-26
Last registration	2023-08-30
Complete history	See info



Registration #1	2011-05-26	29 mi
Registration #2	2014-05-19	30.024 mi
Registration #3	2015-05-11	42.179 mi
Registration #4	2016-05-16	52.259 mi
Registration #5	2017-05-15	60.542 mi
Registration #6	2018-05-21	68.059 mi
Registration #7	2019-02-08	72.467 mi
Registration #8	2020-01-30	77.993 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 mg

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1972 mm
Height	1555 mm
Length	4149 mm
Kerb weight	1374 kg
Max. allowed weight	1743 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13

Engine number

JBEJ0020744