



report date: 2024-03-29

General information

Make	VAUXHALL
Model	AGILA CLUB
Colour	Green
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	114 Nm at 4.400 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 1

Date	2022-03-01
Pictures	25
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-16
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	15
Total items failed	5

MOT #15	2024-04-17 10:08
MOT test number	905908054332
Result	✓ Passed
Next expiry date	2025-04-16

MOT #14	2024-04-08 11:23
MOT test number	749402282800
Result	✗ Failed
Fail	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #13	2023-03-02 17:07
MOT test number	860783033491
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12** 2022-03-04 16:00**MOT test number** 451397441211**Result** ✓ Passed**MOT #11** 2021-06-25 10:41**MOT test number** 644085804483**Result** ✓ Passed**Advice** Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement top mounting (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))**MOT #10** 2020-06-18 15:27**MOT test number** 112357637023**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened lipped (1.1.14 (a) (ii))**MOT #9** 2020-06-18 10:38**MOT test number** 663046010875**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened lipped (1.1.14 (a) (ii))**Fail** Offside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))**MOT #8** 2019-06-04 08:30**MOT test number** 587352832021**Result** ✓ Passed**Advice** Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement top suspension mounting (5.3.4 (a) (i))**MOT #7** 2018-06-14 15:19**MOT test number** 147905918426**Result** ✓ Passed

**MOT #6** 2017-06-21 10:53**MOT test number** 499527459888**Result** ✓ Passed**MOT #5** 2016-06-14 11:17**MOT test number** 715744822217**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2015-06-05 12:00**MOT test number** 209906455107**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-06-23 14:27**MOT test number** 216724774103**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-06-15 09:25**MOT test number** 208056063431**Result** ✓ Passed**MOT #1** 2012-06-12 15:39**MOT test number** 137794162165**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
16 April 2025

Tax status	Valid until 1 July
Days left	62
MOT expiry date	16 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	DN09KCC
Plate since	2019-03-29
Current registration	DN09KCC
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-06-17
Last registration	2024-04-17
Complete history	See info



Registration #1	2009-06-17	27 mi
Registration #2	2012-06-12	17.711 mi
Registration #3	2013-06-15	24.676 mi
Registration #4	2014-06-23	30.353 mi
Registration #5	2015-06-05	33.501 mi
Registration #6	2016-06-14	35.532 mi
Registration #7	2017-06-21	36.986 mi
Registration #8	2018-06-14	37.996 mi
Registration #9	2019-06-04	39.391 mi
Registration #10	2020-06-04	40.786 mi
Registration #11	2021-06-04	42.181 mi
Registration #12	2022-06-04	43.576 mi
Registration #13	2023-06-04	44.971 mi
Registration #14	2024-06-04	46.366 mi
Registration #15	2025-06-04	47.761 mi
Registration #16	2026-06-04	49.156 mi
Registration #17	2027-06-04	50.551 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	990 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1153344