



report date: 2024-03-28

General information

Make	NISSAN
Model	MICRA VISIA
Colour	Grey
Year of manufacture	2014
Top speed	106 mph
0 - 60 mph	13.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	110 Nm at 4.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	115 g/km
CO2 label	C






Internet history

Entry 2


Date	2023-06-22
Pictures	8
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-02-03
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-08-07
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	23
Total items failed	0

MOT #10	2023-08-08 09:08
MOT test number	630360434791
Result	✓ Passed
Next expiry date	2024-08-07

MOT #9	2023-01-28 12:07
MOT test number	194396808819
Result	✓ Passed

MOT #8	2023-01-27 16:59
MOT test number	863716120374
Result	✗ Failed

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice 60 profile tyres fitted to front and 65 profile fitted to rear

MAJOR Offside Front Position lamp not working (4.2.1 (a) (ii))

DANGEROUS Offside Front Tyre has a bulge, caused by separation or partial failure of its structure outer sidewall (5.2.3 (d) (ii))

MAJOR Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #7**

2022-02-12 09:47

MOT test number

807898615260

Result

✓ Passed

- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Nail in tyre
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn to 3mm (5.2.3 (e))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Slight damage to boot floor

MOT #6

2021-02-17 11:31

MOT test number

571618276348

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5

2021-02-17 09:07

MOT test number

287196202283

Result

✗ Failed

- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))



MOT #4	2021-02-15 16:04
MOT test number	507894065543
Result	✗ Failed
MAJOR	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Offside Front wishbone inner bush worn
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #3	2019-05-13 13:34
MOT test number	781755797660
Result	✓ Passed

MOT #2	2018-05-05 08:56
MOT test number	142968511388
Result	✓ Passed

MOT #1	2017-05-27 07:59
MOT test number	684319317286
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
7 August 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	7 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	AK14ULU
Plate since	2019-03-28
Current registration	AK14ULU
Plate since	2019-03-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-05-30
Last registration	2023-08-08
Complete history	See info



Registration #1	2014-05-30	26 mi
Registration #2	2017-05-27	26.084 mi
Registration #3	2018-05-05	34.256 mi
Registration #4	2019-05-13	42.238 mi
Registration #5	2019-05-20	50.227 mi
Registration #6	2021-02-15	56.325 mi
Registration #7	2021-02-17	56.509 mi
Registration #8	2023-08-08	56.509 mi
Registration #9	2023-08-08	56.509 mi
Registration #10	2023-08-08	56.509 mi
Registration #11	2023-08-08	56.509 mi
Registration #12	2023-08-08	56.509 mi
Registration #13	2023-08-08	56.509 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	84%
Children	79%
Pedestrian	58%
Safety systems	57%
Overall rating	75%
Video	see crash video



Dimensions & weight

Width	1665 mm
Height	1520 mm
Length	3825 mm
Wheel base	2450 mm
Kerb weight	925 kg
Max. allowed weight	1425 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	780147B
---------------	---------