




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO GTI
Colour	White
Year of manufacture	2016
Top speed	147 mph
0 - 100 km/h	6.7 seconds
0 - 60 mph	6.7 seconds
Gearbox	6 speed Manual




Engine & fuel consumption

Power	141 kW / 192 HP / 189 BHP
Max. torque	250 Nm at 1.300 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E



**Internet history****Entry 4**




Date	2023-12-08
Pictures	12
Listing price	View report

source: cargurus.co.uk**Entry 3**

Date	2023-12-05
Pictures	0
Listing price	View report

source: carcraft.co.uk**Entry 2**

Date	2023-09-20
Pictures	25
Listing price	View report

source: cargurus.co.uk**Entry 1**

Date	2021-10-12
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-17
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	8
Total items failed	0

MOT #7 2024-03-18 13:31

MOT test number 907143121042

Result ✓ Passed

Next expiry date 2025-03-17

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened BOTH (1.1.14 (a) (ii))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))

MOT #6 2023-09-06 15:15

MOT test number 209979533175

Result ✓ Passed

- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2022-12-07 08:54

MOT test number 705993215977

Result ✓ Passed



MOT #4	2022-12-06 16:11
MOT test number	747639689049
Result	✗ Failed
<div>Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))</div> <div>DANGEROUS Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))</div>	
MOT #3	2021-12-07 15:56
MOT test number	345019555944
Result	✓ Passed
MOT #2	2021-02-23 08:37
MOT test number	122777130675
Result	✓ Passed
MOT #1	2019-09-25 11:01
MOT test number	617692118403
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
17 March 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	17 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 SA66FZB
Plate since	2024-03-29
Current registration	 SA66FZB
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-09-27
Last registration	2024-03-18
Complete history	See info



Registration #1	2016-09-27	11 mi
Registration #2	2019-09-25	21.986 mi
Registration #3	2021-02-23	24.658 mi
Registration #4	2021-12-07	35.142 mi
Registration #5	2022-12-06	46.359 mi
Registration #6		
Registration #7		
Registration #8		
Registration #9		
Registration #10		
Registration #11		
Registration #12		

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1901 mm
Height	1462 mm
Length	3972 mm
Wheel base	2470 mm
Kerb weight	1172 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3

Number of axles	2
Engine number	DAJA014876