




report date: 2024-03-29

General information

Make	VAUXHALL
Model	VIVARO L1H1 2700 SPORTIVE CDTI BITURBO S/S
Colour	Silver
Year of manufacture	2017
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	51.4 mpg
Consumption combined	47.1 mpg
CO2 emission	155 g/km
CO2 label	G





Internet history

Entry 4

Date	2021-11-22
Pictures	20
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 3

Date	2021-08-12
Pictures	0
Listing price	View report

source: [heyicar.co.uk](https://www.heyicar.co.uk)

Entry 2

Date	2021-08-05
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

Entry 1

Date	2021-07-28
Pictures	0
Listing price	View report

source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT expiry date	2024-08-14
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	8
Total items failed	1

MOT #6	2023-08-15 14:13
MOT test number	218941834567
Result	✓ Passed
Next expiry date	2024-08-14
Minor	Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Front Upper Shock absorbers has light misting of oil (5.3.2 (b))

MOT #5	2022-08-12 08:45
MOT test number	282492604175
Result	✓ Passed

MOT #4	2021-08-13 11:25
MOT test number	140979720315
Result	✓ Passed

MOT #3	2021-02-13 12:09
MOT test number	346027691459
Result	✓ Passed
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #2	2021-02-13 10:51
MOT test number	228634199505
Result	✗ Failed
Fail	Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))
Advice	Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #1	2020-02-21 11:26
MOT test number	817601097515
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
14 August 2024

Tax status	Valid until 1 January
Days left	246
MOT expiry date	14 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history


Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 GV66UVP
Plate since	2024-03-29
Current registration	 GV66UVP
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2017-02-20
Last registration	2023-08-15
Complete history	See info



Registration #1	2017-02-20	8 mi
Registration #2	2020-02-21	24.210 mi
Registration #3	2021-02-13	46.185 mi
Registration #4	2021-02-13	46.185 mi
Registration #5	2022-02-20	55.377 mi
Registration #6	2022-02-20	55.377 mi
Registration #7	2022-02-20	55.377 mi
Registration #8	2022-02-20	55.377 mi
Registration #9	2022-02-20	55.377 mi
Registration #10	2022-02-20	55.377 mi
Registration #11	2023-08-15	55.377 mi

More info >



Safety ratings

NCAP rating	★★★★
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	4998 mm
Kerb weight	1743 kg
Max. allowed weight	2820 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	R9M MH - C089503LQI