



RENAULT

FTIOFEO

report date: 2024-03-28

General information

Make	RENAULT
Model	TRAFIC SL27 DCI S/R P/V
Colour	Grey
Year of manufacture	2010
Top speed	96 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	290 Nm at 1.600 rpm
Engine capacity	1.996 cc
Cylinders	4
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	41.5 mpg
Consumption combined	38.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-02-04
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-06-15
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	73
Total items failed	1

MOT #15	2023-06-16 07:56
MOT test number	400390194914
Result	✓ Passed
Next expiry date	2024-06-15
Advice	Brake pedal wearing smooth (1.1.2 (c))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Upper Engine mounting damaged but not to excess Rubber perished (6.1.8 (a) (i))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #14**

2023-06-15 12:03

**MOT test number**

761454302879

**Result****✗ Failed**

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Upper Engine mounting damaged but not to excess Rubber perished (6.1.8 (a) (i))
- MAJOR** Front Brake cable damaged Hand brake cable broken (1.1.15 (a))
- MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- MAJOR** Brake lever has insufficient reserve travel (1.1.2 (a))
- MAJOR** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- MAJOR** Offside Rear Brake cable guide defective and affecting operation (1.1.15 (d))
- DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- MAJOR** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #13**

2022-06-14 08:28

**MOT test number**

615950542674

**Result****✓ Passed**

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Both front jacking points corroded but not weakened or holed
- Advice** Front Tyre worn close to legal limit/worn on edge both worn on edge (5.2.3 (e))
- Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Rear Tyre worn close to legal limit/worn on edge both worn on edge (5.2.3 (e))
- Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

**MOT #12**

2022-05-27 10:55

**MOT test number**

324162951043

**Result****✗ Failed**

- Advice** Rear Tyre worn close to legal limit/worn on edge both worn on edge (5.2.3 (e))
- MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Offside Brake pipe excessively corroded front to rear (1.1.11 (c))
- MAJOR** Nearside Front Brake pipe excessively corroded (1.1.11 (c))
- MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- MAJOR** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- MAJOR** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Offside Front Brake pipe excessively corroded (1.1.11 (c))
- MAJOR** Offside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))
- Advice** Front Tyre worn close to legal limit/worn on edge both worn on edge (5.2.3 (e))
- MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- MAJOR** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Advice** Both front jacking points corroded but not weakened or holed
- MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
- Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #11**

2021-05-26 08:20

**MOT test number**

779557428866

**Result**

✓ Passed

- Advice** BOTH FRONT TYRES ON 3 MILL
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Lower Sub-frame pin or bush worn but not resulting in excessive movement REAR (5.3.4 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #10**

2020-06-05 15:38

**MOT test number**

442082803438

**Result**

✓ Passed

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))



MOT #9	2020-06-04 14:20
MOT test number	397660132832
Result	✗ Failed
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Rear high level stop light not working
Advice	Rear Brake pipe corroded, covered in grease or other material all brake pipes corroded badly (1.1.11 (c))
MAJOR	Central Rear Brake cable damaged cable frayed (1.1.15 (a))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Front wiper rubber split at end

**MOT #8** 2020-05-29 07:42**MOT test number** 832394214295**Result** ✗ Failed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Nearside Rear Wheel bearing has excessive play (5.1.3 (a) (i))
- MAJOR** Exhaust emissions exceed manufacturer's specified limit .8 (8.2.2.2 (a))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #7** 2019-02-07 10:08**MOT test number** 786085232324**Result** ✓ Passed**MOT #6** 2017-06-26 08:39**MOT test number** 701525632948**Result** ✓ Passed



**MOT #5** 2017-06-13 09:13**MOT test number** 951514266579**Result** ✗ Failed**Fail** Nearside Brake pipe excessively corroded main front to rear (3.6.B.2c)**MOT #4** 2016-06-23 13:12**MOT test number** 560923412895**Result** ✓ Passed**Advice** Wiper blades worn**Advice** Near side rear indicator poor (bulb)**MOT #3** 2015-06-26 11:06**MOT test number** 857607375198**Result** ✓ Passed**MOT #2** 2014-06-21 09:50**MOT test number** 935302874137**Result** ✓ Passed**MOT #1** 2013-06-28 14:44**MOT test number** 385589573104**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
15 June 2024

Tax status		Valid until 1 June
Days left		32
MOT expiry date		15 June 2024
Full MOT history		<a href="#">See MOT history</a>



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-06-25
Last registration	2023-06-16
Complete history	<a href="#">See info</a>



Registration #1	2010-06-25	12 mi
Registration #2	2013-06-28	92.315 mi
Registration #3	2014-06-21	115.618 mi
Registration #4	2015-06-26	143.328 mi
Registration #5	2016-06-23	170.435 mi
Registration #6	2017-06-13	193.591 mi
Registration #7	2017-06-26	194.103 mi
Registration #8	2019-02-07	206.833 mi
Registration #9	2020-05-29	208.073 mi
Registration #10	2020-05-29	208.073 mi
Registration #11	2020-05-29	208.073 mi
Registration #12	2020-05-29	208.073 mi
Registration #13	2020-05-29	208.073 mi
Registration #14	2020-05-29	208.073 mi
Registration #15	2020-05-29	208.073 mi
Registration #16	2020-05-29	208.073 mi
Registration #17	2020-05-29	208.073 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Number of axles	2
Engine number	C091993