





report date: 2024-03-29

### General information

Make	VOLVO	
Model	XC60 D4 R-DESIGN PRO AWD	
Colour	Blue	
Year of manufacture	2017	
Top speed	127 mph	
Gearbox	8 speed automatic	

## Engine & fuel consumption

Power	188 BHP	
Max. torque	400 Nm at 1.750 rpm	
Engine capacity	1.969 сс	
Cylinders	4	
Fuel type	Diesel	
Consumption city	48.7 mpg	
Consumption extra urban	58.9 mpg	
Consumption combined	54.3 mpg	
CO2 emission	136 g/km	
CO2 label	E	



CarCheck.co.uk page 1/11




## Internet history

### Entry 2

Date 2021-09-09

Pictures 29

Listing price <u>View report</u>









source: heycar.co.uk

#### Entry 1

Date	2021-08-07
Pictures	29

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-08-21
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	9
Total items failed	2

MOT #6		2023-08-18 12:09
MOT test number	er	760858093071
Result		✓ Passed
Next expiry dat	e	2024-08-21
<b>Advice</b> Front	t Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))
<b>Advice</b> Rear	Brake pad(s) wearing thin (1.1.13 (a) (ii))	
<b>Advice</b> Front	t Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #5		2023-08-14 08:59
MOT test	number	423020664182
Result		<b>×</b> Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a	n) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))		

CarCheck.co.uk page 3/11



MOT #4 2022-08-22 15:25

**MOT test number** 696503291986

Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #3 2021-08-11 09:25

**MOT test number** 858793933887

**Result** 
✓ Passed

**MOT #2** 2020-10-30 15:32

**MOT test number** 298098180931

MOT #1 2020-10-30 09:10

**MOT test number** 666268069971

**Result** X Failed

**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 4/11



## Tax & MOT check

Tax expired: 16 April 2024





Expires: 21 August 2024

Tax status	Expired at 16 April 2024
Days left	13 days too late
MOT expiry date	21 August 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	Н
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e mier metery	
For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full	
manus .	
***************************************	
*********	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	NK SIZ
Plate since	
Current registration	NK SIX
Plate since	
	More info >

CarCheck.co.uk page 8/11



### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



## Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-11-13
Last registration	2023-08-18
Complete history	See info



Registration #1	2017-11-13	27 mi
Registration #2	2020-10-30	10.635 mi
Registration #3	2020-10-30	10.635 mi
Registration #4		11.777 es
Registration #5	2021-08-11	13.099 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
50567	
50569	

## Safety ratings

NCAP rating	****
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



## Dimensions & weight

Width	1999 mm
Height	1658 mm
Length	4688 mm
Wheel base	2865 mm
Kerb weight	1802 kg
Max. allowed weight	2500 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles2Engine number2309655