



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO E (55BHP)
Colour	Black
Year of manufacture	2007
Top speed	94 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg
CO2 emission	138 g/km
CO2 label	E





MOT history

MOT expiry date	2021-09-03
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	9
Total items failed	12

MOT #17	2020-09-03 07:46
MOT test number	361162500695
Result	✓ Passed
Next expiry date	2021-09-03

MOT #16	2019-09-04 15:33
MOT test number	444751557181
Result	✓ Passed

MOT #15	2018-08-20 15:08
MOT test number	746952756137
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2017-08-18 09:10
MOT test number	352103048853
Result	✓ Passed
Advice	Front Bumper insecure

**MOT #13** 2017-08-17 16:52**MOT test number** 548026843002**Result** ✗ Failed**Advice** Front Bumper insecure**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Rear Stop lamp not working (1.2.1b)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Rear Mechanical brake component has restricted free movement (3.5.1k)**Advice** Brake warning indicator lamp illuminated**MOT #12** 2016-08-31 09:21**MOT test number** 596821999790**Result** ✓ Passed**Advice** Front registration plate has a damage**MOT #11** 2015-08-25 13:34**MOT test number** 333621985558**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2015-08-24 11:05**MOT test number** 608284215147**Result** ✗ Failed**Fail** Nearside Side repeater excessively damaged so that it is not visible from a reasonable distance (1.4.A.2e)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)



MOT #9	2014-09-01 10:34
---------------	------------------

MOT test number	268694044229
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #8	2014-09-01 10:34
---------------	------------------

MOT test number	689064644212
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)
--------------------------------	---

MOT #7	2013-08-31 14:39
---------------	------------------

MOT test number	427543643215
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2012-09-01 13:23
---------------	------------------

MOT test number	805475642247
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2011-09-02 16:48
---------------	------------------

MOT test number	539065441227
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2011-09-02 12:21
---------------	------------------

MOT test number	359125441402
------------------------	--------------

Result	✗ Failed
---------------	----------

Fail	Nearside Side repeater not working (1.4.A.2c)
-------------	---

MOT #3	2010-08-21 09:14
---------------	------------------

MOT test number	854673830239
------------------------	--------------

Result	✓ Passed
---------------	----------



MOT #2	2010-08-21 09:14
MOT test number	724803730284
Result	✗ Failed
Pass with rectification	Nearside Side repeater not working (1.4.A.2c)

MOT #1	2010-08-16 10:30
MOT test number	324658120203
Result	✗ Failed
Fail	Offside Headlamp insecure (1.7.3)
Fail	Front registration plate insecure (6.3.1b)
Fail	Nearside Side repeater not working (1.4.A.2c)
Fail	Offside Headlamp aim too low and too far to the right. (1.8)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	LN57XXM
Plate since	2019-06-29
Current registration	LN57XXM
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-09-03
Last registration	2020-09-03
Complete history	See info



Registration #1	2007-09-03	11 mi
Registration #2	2010-08-16	18.418 mi
Registration #3	2010-08-21	18.436 mi
Registration #4	2011-09-02	25.818 mi
Registration #5	2011-09-02	25.818 mi
Registration #6	2012-09-01	37.173 mi
Registration #7	2013-08-31	43.785 mi
Registration #8	2014-09-01	49.285 mi
Registration #9	2015-09-01	55.785 mi
Registration #10	2016-09-01	62.285 mi
Registration #11	2017-09-01	68.785 mi
Registration #12	2018-09-01	75.285 mi
Registration #13	2019-09-01	81.785 mi
Registration #14	2020-09-01	88.285 mi
Registration #15	2021-09-01	94.785 mi
Registration #16	2022-09-01	101.285 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Kerb weight	1186 kg
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	BMD194531