



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 S D V50
Colour	Grey
Year of manufacture	2007
Top speed	118 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	132 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-06-13
Pictures	30
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-07
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	47
Total items failed	13

MOT #19	2023-06-02 09:18
MOT test number	841258883278
Result	✓ Passed
Next expiry date	2024-06-07
Advice	Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #18	2023-05-31 13:21
MOT test number	226880047203
Result	✗ Failed
Advice	Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Fail	Nearside Front Shock absorbers insecurely attached (5.3.2 (a) (i))
Fail	Rear Inner Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MOT #17**

2022-06-08 08:45

MOT test number

370246844291

Result

✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing inner edge as undulations in tread (5.2.3 (d) (ii))
- Advice** Suspension arm ball joint has slight play nearside and offside front lower (5.3.4 (a) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #16

2022-06-07 08:05

MOT test number

129202707370

Result

✗ Failed

- Fail** Offside Headlamp aim too high (4.1.2 (a))
- Fail** Windscreen washer not working (3.5 (a))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Suspension arm ball joint has slight play nearside and offside front lower (5.3.4 (a) (i))
- Fail** All direction indicators incorrect colour (4.4.3 (a))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing inner edge as undulations in tread (5.2.3 (d) (ii))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))



MOT #15

2021-03-16 16:31

MOT test number

476170744345

Result

✓ Passed

- AdviceRear Direction indicator slightly discoloured both sides (4.4.3 (a))
- AdviceRear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))
- AdviceRear Brake disc worn, but not excessively both sides (1.1.14 (a) (i))
- AdviceOffside Rear tyre approaching tread wear indicators
- AdviceFront Direction indicator slightly discoloured both sides (4.4.3 (a))
- AdviceOil leak, but not excessive (8.4.1 (a) (i))
- AdviceUnder tray fitted
- AdviceNearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

**MOT #14**

2021-03-09 16:21

MOT test number

828256002784

Result**✗ Failed**

- Fail** Brake lever excessively worn excessive travel (1.1.15 (b))
- Fail** Front Brake pad(s) less than 1.5 mm thick both sides (1.1.13 (a) (ii))
- Advice** Front Direction indicator slightly discoloured both sides (4.4.3 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear tyre approaching tread wear indicators
- Advice** Front Brake disc worn, but not excessively both sides (1.1.14 (a) (i))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))
- Advice** Rear Direction indicator slightly discoloured both sides (4.4.3 (a))
- Advice** Under tray fitted
- Fail** Fuel system component leaking (6.1.3 (b) (i))
- Advice** Rear Brake disc worn, but not excessively both sides (1.1.14 (a) (i))

MOT #13

2020-03-18 12:57

MOT test number

916752984278

Result**✓ Passed**

- Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #12

2019-03-12 15:04

MOT test number

143112581972

Result**✓ Passed**

**MOT #11** 2019-03-12 10:31**MOT test number** 108332229136**Result** ✗ Failed**Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #10** 2018-03-12 16:07**MOT test number** 557594786187**Result** ✓ Passed**MOT #9** 2017-03-20 15:53**MOT test number** 166104388436**Result** ✓ Passed**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit both edges (4.1.E.1)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)

**MOT #8** 2017-03-20 10:12**MOT test number** 527799645611**Result** ✗ Failed

- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Tyre worn close to the legal limit both edges (4.1.E.1)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)
- Fail** Offside Rear Tyre has ply or cords exposed 205/50/17 (4.1.D.1b)
- Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)

MOT #7 2015-12-16 10:17**MOT test number** 287042925560**Result** ✓ Passed

- Advice** Offside front tyre tread wearing on inner edge

MOT #6 2014-12-17 11:50**MOT test number** 519681854384**Result** ✓ Passed**MOT #5** 2014-12-17 11:50**MOT test number** 468811754400**Result** ✗ Failed

- Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)

MOT #4 2013-12-04 10:15**MOT test number** 475508533305**Result** ✓ Passed



MOT #3	2012-12-08 12:50
MOT test number	516953742370
Result	✓ Passed
MOT #2	2011-12-06 14:21
MOT test number	267270641342
Result	✓ Passed
MOT #1	2010-12-09 13:05
MOT test number	461533940481
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
7 June 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	7 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-12-13
Last registration	2023-06-02
Complete history	See info



Registration #1	2007-12-13	23 mi
Registration #2	2010-12-09	56.243 mi
Registration #3	2011-12-06	71.039 mi
Registration #4	2012-12-08	76.669 mi
Registration #5	2013-12-04	83.534 mi
Registration #6	2014-12-17	90.844 mi
Registration #7	2015-12-16	97.215 mi
Registration #8	2017-03-20	105.713 mi
Registration #9	2017-03-20	105.713 mi
Registration #10	2018-03-12	115.345 mi
Registration #11	2019-03-20	125.713 mi
Registration #12	2020-03-20	135.713 mi
Registration #13	2021-03-20	145.713 mi
Registration #14	2022-03-20	155.713 mi
Registration #15	2023-03-20	165.713 mi
Registration #16	2024-03-20	175.713 mi
Registration #17	2025-03-20	185.713 mi
Registration #18	2026-03-20	195.713 mi
Registration #19	2027-03-20	205.713 mi
Registration #20	2028-03-20	215.713 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4514 mm
Wheel base	2640 mm
Kerb weight	1436 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	71488