





report date: 2024-03-28

General information

Make	AUDI
Model	A3 MPI SE
Colour	Silver
Year of manufacture	2008
Top speed	115 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	101 BHP
Max. torque	148 Nm at 3.800 rpm
Engine capacity	1.595 сс
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	41.5 mpg
CO2 emission	162 g/km
CO2 label	G



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-05

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



GR08BCY
report date: 2024-03-28

MOT history

MOT expiry date	2024-06-13
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	17
Total items failed	8

MOT #15		2023-06-14 12:56
MOT test	number	548634715438
Result		✓ Passed
Next expiry date 2024-06-13		
Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))		
Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))		

MOT #14		2022-02-21 15:36
MOT test	number	522601749835
Result		✓ Passed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Central Rear Seat belt buckle slightly damaged (7.1.2 (d))	

MOT #13		2022-02-21 15:36
MOT test number		950322896628
Result		× Failed
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))		
Pass with rectification	Headlamp aim too low both (4.1.2 (a))	
Advice Central Rear Sea	at belt buckle slightly damaged (7.1.2 (d))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #12 2021-01-27 17:43

MOT test number 193799849346

Result Passed

Advice Engine Cover And Under Trays Fitted Obscuring Some Under Side Components

MOT #11 2021-01-25 13:14

MOT test number 491689985227

Result X Failed

Fail Offside Rear Direction indicator not working (4.4.1 (a) (ii))

Fail Nearside Front Outer Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Offside Rear fog lamp not working (4.5.1 (a) (ii))

Advice Engine Cover And Under Trays Fitted Obscuring Some Under Side Components

MOT #10 2020-01-28 14:42

MOT test number 401709034279

Result ✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9 2019-02-11 14:08

MOT test number 183902039535

Result
✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8 2018-04-03 12:38

MOT test number 521140386857

Result

Passed

Advice Nearside Headlamp deteriorated but light output not reduced (1.7.5a)

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #7 2018-03-17 14:25

MOT test number 364134655177

Result X Failed

Fail Offside Front Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Fail Nearside Registration plate lamp not fitted (1.1.C.1b)

Advice Nearside Headlamp deteriorated but light output not reduced (1.7.5a)

Fail Offside Registration plate lamp not working (1.1.C.1d)

MOT #6 2017-01-30 14:47

MOT test number 629795301279

Result ✓ Passed

MOT #5 2015-06-13 11:46

MOT test number 816294965132

Result
✓ Passed

MOT #4 2014-06-16 14:46

MOT test number 219337564408

Notice Under-trays fitted obscuring some underside components

Notice Engine covers fitted obscuring some components in the engine bay

MOT #3 2013-06-17 12:07

MOT test number 296508363439

Result ✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #2

MOT test number

667516502286

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

 MOT #1
 2011-08-08 09:47

 MOT test number
 786550221259

 Result
 ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	13 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report here .		

	More info >	
Plate changes		
See in this check if this AUDI had different number plates.		
Number of plates	,	
Current registration	NIE NIE	
Plate since		
Current registration	MK MIN MIN	
Plate since		
	More info >	

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-08-14
Last registration	2023-06-14
Complete history	See info



Registration #1	2008-08-14	7 mi
Registration #2	2011-08-08	25.092 mi
Registration #3	2012-07-24	34.890 mi
Registration #4	2013-06-17	40.182 mi
Registration #5	2014-06-16	55.930 mi
Registration #6	2015-06-13	63.043 mi
Registration #7	2017-01-30	73.969 mi
Registration #8	2018-03-17	79.282 mi
Registration #9	2018-04-03	79.282 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		71.777 66
Registration #14		11.777 es
Registration #15		11.177 mi
Registration #16		11.777 es
Registration #17		11.177 ms

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1421 mm
Length	4238 mm
Wheel base	2578 mm
Kerb weight	1185 kg
Max. allowed weight	1745 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles 2

Engine number BSE 705739