



report date: 2024-03-28

General information

Make	BMW
Model	120 120D M SPORT
Colour	Black
Year of manufacture	-
Top speed	142 mph
0 - 60 mph	7.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	174 BHP
Max. torque	350 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	68.9 mpg
Consumption combined	57.7 mpg



LABEL UNKNOWN

**MOT history**

MOT #16	2023-02-16 12:02
MOT test number	326395426893
Result	✓ Passed
Next expiry date	2024-02-15
Advice	Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
Advice	Offside Front Shock absorbers has a reduced damping effect (5.3.2 (d))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Parkbrake has low reserve travel
Advice	Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
Advice	Nearside Front Shock absorbers has a reduced damping effect (5.3.2 (d))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Bumper mountings corroded but not likely to become detached (6.1.4 (a) (i))
Advice	Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

MOT #15	2022-02-08 17:25
MOT test number	116206891790
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Shock absorbers has a reduced damping effect (5.3.2 (d))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #14**

2022-02-08 17:25

MOT test number

991327403783

Result**✗ Failed**

- Advice** Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Shock absorbers has a reduced damping effect (5.3.2 (d))
- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #13

2021-02-11 15:11

MOT test number

632967708141

Result**✓ Passed**

**MOT #12**

2021-02-04 16:16

MOT test number

869939142122

Result**✗ Failed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge 225/40/18/92w (5.2.3 (e))**Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))**Advice** Nearside Front wheel slightly binding, and nearside rear wheel slightly binding.**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Offside Front Brake hose excessively stretched when turning (1.1.12 (b) (ii))**MOT #11**

2019-06-15 10:54

MOT test number

597731227698

Result**✓ Passed****Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Position lamp slightly affected by the operation of another lamp (4.2.3 (c))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #10**

2018-06-13 09:06

MOT test number

883381004227

Result**✓ Passed**

**MOT #9** 2018-06-08 11:45**MOT test number** 226839615156**Result** ✗ Failed

- MAJOR** Brake pad(s) wear indicator illuminated (1.1.13 (a) (i))
- MAJOR** Nearside Front Position lamp not working (4.2.1 (a))
- MAJOR** Offside Parking brake inoperative on one side (1.4.1 (a))
- MAJOR** Front Registration plate does not conform to the specified requirements (0.1 (d))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #8 2017-04-24 13:05**MOT test number** 358375599750**Result** ✓ Passed

- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice** Nearside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)

MOT #7 2015-09-28 08:17**MOT test number** 658333670319**Result** ✓ Passed

**MOT #6** 2014-09-13 15:29**MOT test number** 185066754215**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Both front tyres badly worn on edges 225 40r18 r/flats
- Notice** Under-trays fitted obscuring some underside components
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** O/s/r pad sensor not fitted to pad
- Notice** Engine covers fitted obscuring some components in the engine bay

MOT #5 2014-09-13 12:43**MOT test number** 885346754293**Result** ✗ Failed

- Notice** O/s/r pad sensor not fitted to pad
- Notice** Engine covers fitted obscuring some components in the engine bay
- Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Both front tyres badly worn on edges 225 40r18 r/flats
- Notice** Under-trays fitted obscuring some underside components
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2013-11-29 15:23**MOT test number** 997653333385**Result** ✓ Passed



MOT #3	2012-09-12 12:41
MOT test number	317456052269
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2011-09-06 13:39
MOT test number	386699841419
Result	✓ Passed

MOT #1	2010-08-09 11:39
MOT test number	334521420466
Result	✓ Passed



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-08-22
Last registration	2023-02-16
Complete history	See info



Registration #1	2007-08-22	8 mi
Registration #2	2010-08-09	49.921 mi
Registration #3	2011-09-06	63.029 mi
Registration #4	2012-09-12	72.428 mi
Registration #5	2013-11-29	85.390 mi
Registration #6	2014-09-13	94.088 mi
Registration #7	2014-09-13	94.088 mi
Registration #8	2015-09-28	100.832 mi
Registration #9	2017-04-24	115.147 mi
Registration #10	2019-05-29	121.277 mi
Registration #11	2019-05-29	121.277 mi
Registration #12	2019-05-29	121.277 mi
Registration #13	2019-05-29	121.277 mi
Registration #14	2019-05-29	121.277 mi
Registration #15	2019-05-29	121.277 mi
Registration #16	2019-05-29	121.277 mi
Registration #17	2019-05-29	121.277 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1748 mm
Height	1421 mm
Length	4239 mm
Wheel base	2660 mm
Kerb weight	1450 kg
Max. allowed weight	1865 kg

Additional information

Fuel tank capacity	51 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	95586577