



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I20 T-GDI TURBO EDITION
Colour	White
Year of manufacture	2017
Top speed	116 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	171 Nm at 4.000 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	49.6 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 2


Date	2021-09-26
Pictures	11
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-08-09
Pictures	12
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-08-27
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	12
Total items failed	6

MOT #6	2023-08-28 15:11
MOT test number	330545606907
Result	✓ Passed
Next expiry date	2024-08-27

MOT #5	2022-03-29 12:52
MOT test number	815994476599
Result	✓ Passed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #4	2021-03-30 13:42
MOT test number	669447033154
Result	✓ Passed
Minor	Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
Advice	Nearside sill damaged
Advice	Offside Front Tyre worn close to legal limit/worn on edge tread depth 1.8mm (5.2.3 (e))

**MOT #3** 2021-03-23 14:56**MOT test number** 494684341298**Result** ✗ Failed**Advice** Nearside sill damaged**Advice** Offside Front Tyre worn close to legal limit/worn on edge tread depth 1.8mm (5.2.3 (e))**Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #2** 2020-03-09 08:58**MOT test number** 841406709678**Result** ✓ Passed**MOT #1** 2020-03-06 10:31**MOT test number** 328081734543**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
27 August 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	27 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-03-10
Last registration	2023-08-28
Complete history	See info



Registration #1	2017-03-10	27 mi
Registration #2	2020-03-06	116.776 mi
Registration #3	2020-03-09	116.780 mi
Registration #4	2021-03-23	138.373 mi
Registration #5	2021-03-30	138.525 mi
Registration #6	2023-08-28	138.525 mi
Registration #7	2023-08-28	138.525 mi
Registration #8	2023-08-28	138.525 mi
Registration #9	2023-08-28	138.525 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	85%
Children	73%
Pedestrian	79%
Safety systems	64%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1734 mm
Height	1474 mm
Length	4035 mm
Wheel base	2570 mm
Kerb weight	1065 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G3LCGP035966