



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 ZEST
Colour	Silver
Year of manufacture	-
Top speed	98 mph
0 - 60 mph	15.1 seconds
Gearbox	7 speed Manual

Engine & fuel consumption

Power	60 BHP
Max. torque	94 Nm at 2.700 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	56.5 mpg
Consumption combined	45.6 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-12-30
Pictures	5
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #19	2021-12-11 12:27
MOT test number	250274554378
Result	✓ Passed
Next expiry date	2022-12-29
Advice	Rear Tank strap corroded
Advice	Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
Advice	Rear Axle corroded
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #18	2021-12-09 15:02
MOT test number	373281030913
Result	✗ Failed
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Rear Axle corroded
Advice	Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
Fail	Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))
Advice	Rear Tank strap corroded
Fail	Offside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))

**MOT #17**

2020-12-30 10:08

MOT test number

321274407417

Result

✓ Passed

- Advice** Offside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))
- Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Central Exhaust mounting defective (6.1.2 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Play in steering rack inner joint(s)
- Advice** Oil leak, but not excessive engine/gearbox (8.4.1 (a) (i))
- Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16

2020-12-30 10:08

MOT test number

702380843920

Result

✗ Failed

- Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Play in steering rack inner joint(s)
- Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Pass with rectification** Nearside Side repeater incorrect colour (4.4.3 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Central Exhaust mounting defective (6.1.2 (a))
- Advice** Offside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive engine/gearbox (8.4.1 (a) (i))

**MOT #15** 2019-12-19 15:01**MOT test number** 960742370961**Result** ✓ Passed**Advice** Oil leak, but not excessive suspect crank seal (gearbox side) (8.4.1 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear fuel tank strap corroded**Advice** Rear Shock absorbers has a slightly worn bush both rear's (5.3.2 (c))**Advice** Rear axle corroded**MOT #14** 2018-12-20 15:23**MOT test number** 283833820649**Result** ✓ Passed**MOT #13** 2017-12-12 11:23**MOT test number** 421523771279**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear exhaust box corroded**MOT #12** 2016-12-28 12:24**MOT test number** 354635778930**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Front exhaust bracket partially fractured**Advice** Rear Rear silencer heavily corroded

**MOT #11** 2016-12-28 12:24**MOT test number** 457830600603**Result** ✗ Failed**Advice** Rear Rear silencer heavily corroded**Pass with rectification** Rear fog lamp not working (1.3.2b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Front exhaust bracket partially fractured**MOT #10** 2015-12-16 11:06**MOT test number** 580610458892**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #9** 2015-12-16 08:34**MOT test number** 895583997522**Result** ✗ Failed**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #8** 2014-12-09 09:53**MOT test number** 746543244366**Result** ✓ Passed**Notice** OSF-wiper arm worn**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**Notice** Play in steering rack inner joint(s)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Notice** Oil leak**Advice** Shock absorber has a slightly worn bush (2.7.4)**MOT #7** 2013-12-11 17:16**MOT test number** 589475043324**Result** ✓ Passed**Advice** Offside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)**MOT #6** 2012-11-30 10:27**MOT test number** 426315332438**Result** ✓ Passed**MOT #5** 2011-12-02 12:00**MOT test number** 465356031401**Result** ✓ Passed**MOT #4** 2010-12-04 12:11**MOT test number** 361948830309**Result** ✓ Passed



MOT #3	2009-12-11 18:52
MOT test number	472065749499
Result	✓ Passed
MOT #2	2008-12-06 10:02
MOT test number	564591748342
Result	✓ Passed
MOT #1	2007-12-13 15:19
MOT test number	421797647494
Result	✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	WL54LJY
Plate since	2019-03-28
Current registration	WL54LJY
Plate since	2019-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2004-12-29
Last registration	2021-12-11
Complete history	See info



Registration #1	2004-12-29	28 mi
Registration #2	2007-12-13	23.718 mi
Registration #3	2008-12-06	32.820 mi
Registration #4	2009-12-11	42.675 mi
Registration #5	2010-12-04	54.072 mi
Registration #6	2011-12-02	63.793 mi
Registration #7	2012-11-30	70.582 mi
Registration #8	2013-12-11	80.842 mi
Registration #9	2014-12-09	87.447 mi
Registration #10	2015-12-16	90.888 mi
Registration #11	2015-12-16	90.888 mi
Registration #12	2016-12-16	90.888 mi
Registration #13	2017-12-16	90.888 mi
Registration #14	2018-12-16	90.888 mi
Registration #15	2019-12-16	90.888 mi
Registration #16	2020-12-16	90.888 mi
Registration #17	2021-12-16	90.888 mi
Registration #18	2022-12-16	90.888 mi
Registration #19	2023-12-16	90.888 mi
Registration #20	2024-12-16	90.888 mi
Registration #21	2025-12-16	90.888 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	985 kg
Max. allowed weight	1405 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	5

Number of axles	2
Engine number	FP7N4595647