



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	SCIROCCO TDI BLUEMOTION TECHNOLOGY
Colour	Black
Year of manufacture	2013
Top speed	129 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	67.3 mpg
Consumption combined	55.4 mpg
CO2 emission	118 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-06-07
Pictures	24
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-05-12
MOT pass rate	53 %
MOT passed	8
Failed MOT tests	7
Total advice items	36
Total items failed	3

MOT #15 2023-05-11 13:32**MOT test number** 200966837324**Result** ✓ Passed**Next expiry date** 2024-05-12**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))**MOT #14** 2023-05-10 11:25**MOT test number** 880182179787**Result** ✗ Failed**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #13** 2022-05-13 11:42**MOT test number** 576913098000**Result** ✓ Passed**Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #12** 2021-06-18 08:39**MOT test number** 875937224902**Result** ✓ Passed**MOT #11** 2020-11-10 14:17**MOT test number** 239984372289**Result** ✓ Passed**Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**MOT #10** 2020-11-10 10:29**MOT test number** 841379477576**Result** ✗ Failed**Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))**MAJOR** Offside Rear Parking brake inoperative on one side (1.4.1 (a))**MOT #9** 2019-10-30 16:25**MOT test number** 520455821381**Result** ✓ Passed**Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #8** 2019-10-30 11:00**MOT test number** 975964830498**Result** ✗ Failed**MAJOR** Rear fog lamp tell-tale not working (4.9.1 (a) (ii))**MAJOR** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**MAJOR** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))**MAJOR** Horn not working (7.7 (a) (ii))**Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**MAJOR** Rear fog lamp switch inoperative (4.5.3 (a) (ii))**MOT #7** 2018-10-08 07:35**MOT test number** 409099999488**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2018-10-08 07:35**MOT test number** 765150222327**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2018-09-27 10:15**MOT test number** 916769088952**Result** ✗ Failed**MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Headlamp aim not tested (4.1.2 (b))**MAJOR** Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Vehicles internal headlight adjuster altered to recheck lights**MAJOR** Nearside Side repeater not working (4.4.1 (a) (ii))**MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** TPMS lamp illuminated, not indicating a fault**MOT #4** 2017-09-19 13:33**MOT test number** 972350995276**Result** ✓ Passed**Advice** Advise under trays fitted obscuring some under side components**MOT #3** 2017-09-19 09:32**MOT test number** 952171745517**Result** ✗ Failed**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Advise under trays fitted obscuring some under side components



MOT #2	2016-10-11 08:52
MOT test number	546156217070
Result	✓ Passed
Advice	Advise under trays fitted obscuring some under side components

MOT #1	2016-10-11 08:40
MOT test number	201182009195
Result	✗ Failed
Fail	Nearside Side repeater not working (1.4.A.2c)
Advice	Advise under trays fitted obscuring some under side components



Tax & MOT check

✓
Taxed

Tax due:
1 March 2025

✓
MOT

Expires:
12 May 2024

Tax status	Valid until 1 March
Days left	307
MOT expiry date	12 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2013-11-07
Last registration	2023-05-11
Complete history	See info



Registration #1	2013-11-07	18 mi
Registration #2	2016-10-11	36.393 mi
Registration #3	2016-10-11	36.393 mi
Registration #4	2017-09-19	53.042 mi
Registration #5	2017-09-19	53.042 mi
Registration #6	2018-09-27	67.852 mi
Registration #7	2018-10-08	68.496 mi
Registration #8	2018-10-08	68.496 mi
Registration #9	2019-10-30	82.041 mi
Registration #10	2019-10-30	82.041 mi
Registration #11	2019-10-30	82.041 mi
Registration #12	2019-10-30	82.041 mi
Registration #13	2019-10-30	82.041 mi
Registration #14	2019-10-30	82.041 mi
Registration #15	2019-10-30	82.041 mi
Registration #16	2019-10-30	82.041 mi
Registration #17	2019-10-30	82.041 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1404 mm
Length	4256 mm
Wheel base	2578 mm
Kerb weight	1318 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	CFHC520511