



General information

Make	VOLKSWAGEN
Model	EOS GTI PIRELLI
Colour	Silver
Year of manufacture	2008
Top speed	152 mph
0 - 60 mph	6.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	230 BHP
Max. torque	300 Nm at 2.200 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.8 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.0 mpg
CO2 emission	194 g/km
CO2 label	J






Internet history

Entry 1

Date	2021-06-13
Pictures	18
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-18
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	44
Total items failed	2

MOT #16	2024-04-19 15:35
MOT test number	933597786162
Result	✓ Passed
Next expiry date	2025-04-18
Advice	Items removed from driver's view prior to test Phone holder in screen
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Play in steering rack inner joint(s)
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #15	2024-04-19 13:41
MOT test number	878226654611
Result	✗ Failed
Advice	Items removed from driver's view prior to test Phone holder in screen
Fail	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Play in steering rack inner joint(s)
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #14** 2023-02-13 11:32**MOT test number** 632660714812**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #13** 2022-02-14 11:16**MOT test number** 200024994426**Result** ✓ Passed**Advice** Both rear tyres perishing**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #12** 2021-02-02 15:29**MOT test number** 334179463460**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge and perished to sidewalls (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #11** 2020-02-17 10:49**MOT test number** 904056512976**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10**

2019-02-18 12:11

MOT test number

741228343945

Result

✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing worn on inner edge (5.2.3 (d) (ii))**MOT #9**

2018-02-01 10:13

MOT test number

106461677509

Result

✓ Passed

Advice O/S/F tyre wearing thin approx. 2mm 235/45/17**Advice** O/S/R tyre perished and wearing thin on inner edge**Advice** Oil level low**Advice** Engine covers & under trays fitted obscuring some vehicle components from view**Advice** N/S/R tyre perished**Advice** Rear brake pads wearing thin approx. 80% worn**MOT #8**

2017-02-13 10:00

MOT test number

772467668418

Result

✓ Passed

Advice Nearside Rear Tyre cracked and perished**Advice** Front brake disc worn, pitted or scored, but not seriously weakened Slightly lipped (3.5.1i)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit @3mm (4.1.E.1)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened Lipped (3.5.1i)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Rear bush just starting to separate (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit @3mm & cracked and perished (4.1.E.1)

**MOT #7** 2016-02-12 11:44**MOT test number** 856217715507**Result** ✓ Passed**Advice** Nearside Rear Tyre wearing on very inner edge**Advice** Under-trays fitted obscuring some underside components**Advice** Offside Rear Tyre wearing on very inner edge**MOT #6** 2015-02-10 10:14**MOT test number** 956651045096**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #5** 2014-02-13 15:26**MOT test number** 647454144014**Result** ✓ Passed**Notice** Nsf seat belt starting to fluff on edge of belt.**MOT #4** 2013-02-20 15:20**MOT test number** 286201253027**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #3** 2012-02-17 11:25**MOT test number** 717948942012**Result** ✓ Passed



MOT #2	2011-02-18 12:01
MOT test number	526469241041
Result	✓ Passed

MOT #1	2011-02-15 14:40
MOT test number	158946741090
Result	✗ Failed

Fail

An item not tested (Manual)



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
18 April 2025

Tax status	Valid until 1 June
Days left	34
MOT expiry date	18 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-




Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-29
Current registration	 XXXXXX
Plate since	2020-01-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-03-01
Last registration	2024-04-19
Complete history	See info



Registration #1	2008-03-01	27 mi
Registration #2	2011-02-15	11.543 mi
Registration #3	2011-02-18	11.543 mi
Registration #4	2012-02-17	13.978 mi
Registration #5	2013-02-20	16.240 mi
Registration #6	2014-02-13	18.430 mi
Registration #7	2015-02-10	20.271 mi
Registration #8	2016-02-12	22.316 mi
Registration #9	2017-02-13	24.351 mi
Registration #10	2018-02-13	26.386 mi
Registration #11	2019-02-13	28.421 mi
Registration #12	2020-02-13	30.456 mi
Registration #13	2021-02-13	32.491 mi
Registration #14	2022-02-13	34.526 mi
Registration #15	2023-02-13	36.561 mi
Registration #16	2024-02-13	38.596 mi
Registration #17	2025-02-13	40.631 mi
Registration #18	2026-02-13	42.666 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1469 mm
Length	4216 mm
Wheel base	2578 mm
Kerb weight	1328 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BYD 011009