





General information

Make	VOLKSWAGEN
Model	AMAROK DC TDI HIGHLINE 4MOTION
Colour	Beige
Year of manufacture	2012
Top speed	112 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.1 mpg
Consumption extra urban	40.4 mpg
Consumption combined	35.8 mpg
CO2 emission	216 g/km
CO2 label	К







Internet history

Entry 1	
Date	2021-08-05
Pictures	12
Listing price	View report









source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-05
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	12
Total items failed	11

MOT #14	2023-09-05 12:23
MOT test number	161240758008
Result	🗸 Passed
Next expiry date 2024-09	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #13	2023-09-05 10:01
MOT test number	519311690047
Result	🗙 Failed
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor (b) (i)) Nearside Registration plate lamp inoperative in the case of multiple lamps or	light sources (4.7.1
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #12	2022-09-06 11:24
MOT test number	115619859281
Result	✓ Passed
AdviceNearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))AdviceRusty rear suspension shock absorbers	



A062	YYS
report date:	2024-03-28

MOT #11	2022-09-03 08:40
MOT test number	548542157939
Result	🗙 Failed
Fail Nearside Headlamp aim not tested (4.1.2 (b))	
FailRear fog lamp not working (4.5.1 (a) (ii))	
Advice Rusty rear suspension shock absorbers	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Fail Front Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))	

MOT #10	2021-08-20 14:27
MOT test	number 504586236573
Result	✓ Passed
Advice	Offside Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

МОТ #9	2021-08-19 09:39
MOT test number	280258088881
Result	🗙 Failed
Advice Nearside Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	(a) (ii))
Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
Advice Offside Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a	a) (ii))
Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	





MOT #8		2021-01-06 17:08
MOT test number		794803070169
Result		🗸 Passed
MOT #7		2020-01-06 18:47
MOT test number		870589275135
Result		✓ Passed
MOT #6		2019-01-05 13:10
MOT test number		828966196234
Result		✓ Passed
MOT #5		2018-01-07 12:39
MOT test number		565488756390
Result		✓ Passed
MOT #4		2018-01-07 12:39
MOT test number		664805741030
Result		🗙 Failed
Pass with rectification	Nearside Headlamp not working on dipped beam (1.7.5a)	
MOT #3		2016-11-23 16:01
MOT test number		116872305131

Result

MOT #2	2015-11-20 10:18
MOT test number	124688423785
Result	✓ Passed

🗸 Passed





MOT #1		2015-11-20 10:18
MOT test number		787833544715
Result		🗙 Failed
Pass with rectification	Offside Headlamp not working on dipped beam (1.7.5a)	



Tax & MOT check

✓ Taxed Tax due: 1 January 2025	✓ MOT Expires: 5 September 2024
Tax status	Valid until 1 January
Days left	246
MOT expiry date	5 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEED ON
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
Date	OLE I
Category	AM
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

ANALY AND A ANALY	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate sites	





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-12-19
Last registration	2023-09-05
Complete history	See info



Registration #1	2012-12-19	23 mi
Registration #2	2015-11-20	29.390 mi
Registration #3	2015-11-20	29.390 mi
Registration #4	2016-11-23	37.982 mi
Registration #5	2018-01-07	45.927 mi
Registration #6	2018-01-07	45.927 mi
Registration #7	2019-01-05	59.423 mi
Registration #8	2020-01-06	77.236 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		11.777 mi
Registration #14		11.777 est
Registration #15		11.777 mi
Registration #16		

More info \rightarrow





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	
Adult	86%
Children	64%
Pedestrian	47%
Safety systems	57%
Overall rating	71%
Video	see crash video



Dimensions & weight	
Width	2228 mm
Height	1834 mm
Length	5254 mm
Kerb weight	2106 kg
Max. allowed weight	4004 kg
Additional information	

Fuel tank capacity	80
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
CarCheck.co.uk	page 13/13