



report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO EVO GP
Colour	Black
Year of manufacture	2011
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-07-25
Pictures	29
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-22
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	52
Total items failed	3

MOT #14	2023-07-22 11:27
---------	------------------

MOT test number	680040877747
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-07-22
------------------	------------

- AdviceFront Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- AdviceRear Coil spring corroded Both sides (5.3.1 (b) (i))
- AdviceRear Registration plate deteriorated but not likely to be misread (0.1 (b))
- AdviceOil leak, but not excessive Gearbox (8.4.1 (a) (i))
- AdviceNearside Front Coil spring corroded (5.3.1 (b) (i))
- AdviceOffside Front Inner Tyre worn close to legal limit/worn on edge Edge bald (5.2.3 (e))
- AdviceFront Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- AdviceFront Registration plate deteriorated but not likely to be misread (0.1 (b))
- AdviceOil leak, but not excessive Engine (8.4.1 (a) (i))

**MOT #13**

2022-07-04 14:30

MOT test number

280034140428

Result

✓ Passed

- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Lower engine/gearbox areas show oil/fluid contamination.

MOT #12

2022-07-02 13:30

MOT test number

576526978225

Result

✗ Failed

- Advice** Lower engine/gearbox areas show oil/fluid contamination.
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Items removed from driver's view prior to test
- MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #11

2021-07-23 11:41

MOT test number

546616777254

Result

✓ Passed

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #10**

2020-11-13 16:00

MOT test number

875190191199

Result

✓ Passed

Advice Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Inside edge (5.2.3 (e))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Exhaust condition**MOT #9**

2020-11-13 08:43

MOT test number

370537089576

Result

✗ Failed

Advice Exhaust condition**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Inside edge (5.2.3 (e))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**MOT #8**

2019-11-22 08:37

MOT test number

213625968239

Result

✓ Passed

Advice Exhaust condition

**MOT #7** 2018-11-27 08:50**MOT test number** 116267162828**Result** ✓ Passed**Advice** O/s/r and n/s/r tyres age related cracking to tread**Advice** Exhaust condition**MOT #6** 2017-09-19 08:16**MOT test number** 226383055710**Result** ✓ Passed**Advice** O/s/r and n/s/r tyres age related cracking to tread**Advice** Exhaust condition**MOT #5** 2016-09-15 15:30**MOT test number** 667752780615**Result** ✓ Passed**Advice** O/s/f and n/s/f brake discs scored inside faces**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Exhaust condition**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2016-09-15 07:55**MOT test number** 653493426196**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Exhaust condition**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** O/s/f and n/s/f brake discs scored inside faces**MOT #3** 2015-09-30 08:44**MOT test number** 896338267563**Result** ✓ Passed**Advice** Nearside Front brake disc modified but not seriously weakened (3.5.1n)**MOT #2** 2015-09-23 13:41**MOT test number** 487534797994**Result** ✗ Failed**Advice** Nearside Front brake disc modified but not seriously weakened (3.5.1n)**Fail** Nearside Front coil spring broken (2.4.C.1a)



MOT #1 2014-09-19 09:23

MOT test number 807222064269

Result ✓ Passed

- Notice** Coolant leak
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Gearbox oil leak from gear turrut oil seal
- Notice** Vehicle's internal headlight adjuster altered to recheck lights



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
22 July 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	22 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-09-21
Last registration	2023-07-22
Complete history	See info



Registration #1	2011-09-21	15 mi
Registration #2	2014-09-19	11.101 mi
Registration #3	2015-09-23	14.531 mi
Registration #4	2015-09-30	14.531 mi
Registration #5	2016-09-15	19.368 mi
Registration #6	2016-09-15	19.368 mi
Registration #7	2017-09-19	24.700 mi
Registration #8	2018-11-27	26.155 mi
Registration #9	2019-09-23	26.155 mi
Registration #10	2019-09-23	26.155 mi
Registration #11	2019-09-23	26.155 mi
Registration #12	2019-09-23	26.155 mi
Registration #13	2019-09-23	26.155 mi
Registration #14	2019-09-23	26.155 mi
Registration #15	2019-09-23	26.155 mi
Registration #16	2019-09-23	26.155 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1585 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	9639502