



report date: 2024-03-29

General information

Make	VAUXHALL
Model	MOVANO F3500 L2H2 P/V CDTi
Colour	White
Year of manufacture	2012
Top speed	134 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	285 Nm at 1.250 rpm
Engine capacity	2.299 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.5 mpg
Consumption extra urban	37.7 mpg
Consumption combined	34.0 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-10
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2023-08-02
MOT pass rate	57 %
MOT passed	8
Failed MOT tests	6
Total advice items	36
Total items failed	20

MOT #14	2022-08-03 09:25
MOT test number	592415653253
Result	✓ Passed
Next expiry date	2023-08-02
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #13	2022-07-30 11:42
MOT test number	639982500655
Result	✗ Failed
Fail	Offside Rear Position lamp not working (4.2.1 (a) (ii))
Fail	Offside Rear Direction indicator not working (4.4.1 (a) (ii))
Fail	Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Fail	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii))
Fail	Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

**MOT #12**

2022-03-07 11:54

MOT test number

528595097240

Result**✗ Failed**

- Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Fail** Offside Rear Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))

MOT #11

2021-03-01 16:00

MOT test number

632430970435

Result**✓ Passed**

- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #10

2020-02-25 10:55

MOT test number

135718597596

Result**✓ Passed**

- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Under trays fitted
- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Advice** Wheel covers fitted
- Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (D) bush (5.3.4 (a) (i))

**MOT #9**

2020-02-25 10:55

MOT test number

118566351710

Result**✗ Failed**

- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))
- Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Wheel covers fitted
- Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (D) bush (5.3.4 (a) (i))
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))
- Advice** Under trays fitted

MOT #8

2019-02-11 12:47

MOT test number

748722290373

Result**✓ Passed**

- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Nearside side door handle damaged
- Advice** Under trays fitted

**MOT #7** 2019-02-11 12:47**MOT test number** 404845987825**Result** ✗ Failed

- Advice** Nearside side door handle damaged
- Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))
- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Under trays fitted
- Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))

MOT #6 2018-02-07 12:11**MOT test number** 833628006156**Result** ✓ Passed

- Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Nearside sliding door cannot be opened from outside
- Advice** Offside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front anti roll bar mounting bush has some wear

MOT #5 2018-02-02 10:02**MOT test number** 829263188698**Result** ✗ Failed

- Advice** Offside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front anti roll bar mounting bush has some wear
- Fail** Nearside Front Steering rack gaiter insecure (2.2.D.2d)
- Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Nearside sliding door cannot be opened from outside



MOT #4	2017-01-27 16:08
MOT test number	248133322051
Result	✓ Passed
Advice	Emissions to clean to register on meter.

MOT #3	2017-01-27 12:25
MOT test number	783108283187
Result	✗ Failed
Fail	Offside Rear Registration plate lamp not working (1.1.C.1d)
Fail	Nearside Front Front constant velocity joint is insecure (2.5.C.1b)
Advice	Emissions to clean to register on meter.
Fail	Offside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #2	2016-02-08 15:56
MOT test number	492254640875
Result	✓ Passed

MOT #1	2015-03-27 11:34
MOT test number	309316885047
Result	✓ Passed
Notice	N/S Rear tyre wearing on outer edge of tread area
Notice	Nail in offside rear tyre



Tax & MOT check

✕
Untaxed

Tax expired:
31 January 2023

✕
MOT

Expired:
2 August 2023

Tax status		Expired at 31 January 2023
Days left		454 days too late
MOT expiry date		2 August 2023
Full MOT history		See MOT history



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-03-30
Last registration	2022-08-03
Complete history	See info



Registration #1	2012-03-30	11 mi
Registration #2	2015-03-27	67.685 mi
Registration #3	2016-02-08	78.229 mi
Registration #4	2017-01-27	93.185 mi
Registration #5	2017-01-27	93.185 mi
Registration #6	2018-02-02	120.864 mi
Registration #7	2018-02-07	120.864 mi
Registration #8	2019-02-11	132.197 mi
Registration #9	2019-05-29	151.277 mi
Registration #10	2019-05-29	151.277 mi
Registration #11	2019-05-29	151.277 mi
Registration #12	2019-05-29	151.277 mi
Registration #13	2019-05-29	151.277 mi
Registration #14	2019-05-29	151.277 mi
Registration #15	2019-05-29	151.277 mi
Registration #16	2019-05-29	151.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	85%
Children	78%
Pedestrian	41%
Safety systems	86%
Overall rating	75%
Video	see crash video



Dimensions & weight

Width	2470 mm
Height	2500 mm
Length	5548 mm
Kerb weight	1890 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	C036631