



report date: 2024-03-29

General information

Make	FIAT
Model	500 C MULTIJET C LOUNGE
Colour	Black
Year of manufacture	2012
Top speed	112 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	56.5 mpg
Consumption extra urban	85.6 mpg
Consumption combined	72.4 mpg
CO2 emission	104 g/km
CO2 label	B







Internet history

Entry 2

Date	2021-09-06
Pictures	12
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-30
Pictures	14
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2022-08-02
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	27
Total items failed	9

MOT #12	2021-08-03 13:02
MOT test number	528953782753
Result	✓ Passed
Next expiry date	2022-08-02

MOT #11	2020-11-09 14:18
MOT test number	509215434085
Result	✓ Passed
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #10**

2020-11-06 08:40

MOT test number

716453346502

Result**✗ Failed**

Advice Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

Advice Rear BUMP STOPS INSECURE

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Nearside Rear Shock absorbers has a slightly worn bush CLOSE TO EXCESS (5.3.2 (c))

Fail Driver's view of the road through the swept area of the windscreen materially affected by an obstruction OBJECTS HUNG ON MIRROR (3.1 (a) (ii))

Fail Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Rear Exhaust mounting defective CLAMP CORRODED (6.1.2 (a))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Fail Offside Rear Service brake excessively binding (1.2.1 (f))

Advice EXHAUST CORRODED

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Offside Rear Shock absorbers has a slightly worn bush CLOSE TO EXCESS (5.3.2 (c))

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #9

2019-10-18 09:07

MOT test number

848717001372

Result**✓ Passed**

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #8** 2019-10-10 09:12**MOT test number** 414723772313**Result** ✗ Failed**Advice** Nearside Front Upper Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Offside Front Upper Shock absorbers has a slightly worn bush (5.3.2 (c))**Fail** Brake fluid contaminated (1.8 (a))**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #7** 2018-10-12 16:23**MOT test number** 608178497918**Result** ✓ Passed**MOT #6** 2018-03-28 10:05**MOT test number** 554447857676**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Rear Outer handbrake cable split**Advice** Rear Tyres starting to perish**MOT #5** 2018-03-28 09:01**MOT test number** 711781676495**Result** ✗ Failed**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Offside Rear Outer handbrake cable split**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Rear Tyres starting to perish

**MOT #4** 2017-03-20 09:45**MOT test number** 293464885265**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Outer door handle coming away**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2016-03-21 11:23**MOT test number** 576661447033**Result** ✓ Passed**Advice** Both front wipers split but clearing the screen**Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**MOT #2** 2015-03-31 16:47**MOT test number** 595340695075**Result** ✓ Passed**MOT #1** 2015-03-24 09:32**MOT test number** 555543185027**Result** ✗ Failed**Notice** Front wiper blades starting to split**Notice** O/s handbrake cable split**Fail** Parking brake lever has no reserve travel (3.1.6b)



Tax & MOT check

×

Untaxed

Tax expired:
1 September 2022

×

MOT

Expired:
2 August 2022

Tax status

Expired at 1 September

Days left

606 days too late

MOT expiry date

2 August 2022

Full MOT history

[See MOT history](#)

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2019-03-29
Current registration	XXXXX
Plate since	2019-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-03-28
Last registration	2021-08-03
Complete history	See info



Registration #1	2012-03-28	28 mi
Registration #2	2015-03-24	25.568 mi
Registration #3	2015-03-31	25.755 mi
Registration #4	2016-03-21	32.998 mi
Registration #5	2017-03-20	46.585 mi
Registration #6	2018-03-28	53.338 mi
Registration #7	2018-03-28	53.338 mi
Registration #8	2018-10-12	53.781 mi
Registration #9	2019-05-20	55.277 mi
Registration #10	2019-05-20	55.277 mi
Registration #11	2019-05-20	55.277 mi
Registration #12	2019-05-20	55.277 mi
Registration #13	2019-05-20	55.277 mi
Registration #14	2019-05-20	55.277 mi
Registration #15	2019-05-20	55.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	1020 kg
Max. allowed weight	1435 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	4683354