




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOUAREG SE TDI DPF
Colour	Grey
Year of manufacture	2007
Top speed	114 mph
0 - 60 mph	11.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	172 BHP
Max. torque	400 Nm at 2.250 rpm
Engine capacity	2.461 cc
Cylinders	5
Fuel type	Diesel
Consumption city	22.8 mpg
Consumption extra urban	36.2 mpg
Consumption combined	29.7 mpg
CO2 emission	275 g/km
CO2 label	M





Internet history

Entry 2


Date	2023-12-12
Pictures	8



source: g3remarketing.co.uk

Entry 1

Date	2021-06-12
Pictures	81
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-07
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	14
Total items failed	9

MOT #18	2023-05-24 08:46
MOT test number	504149255296
Result	✓ Passed
Next expiry date	2024-06-07
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #17	2022-06-08 12:16
MOT test number	416069298696
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #16	2021-09-01 14:20
MOT test number	645837890642
Result	✓ Passed

MOT #15	2021-09-01 08:54
MOT test number	769720883833
Result	✗ Failed
Advice	Offside Front Outer Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Outer Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #14** 2020-09-04 13:18**MOT test number** 296609556477**Result** ✓ Passed**MOT #13** 2019-09-10 12:16**MOT test number** 547953522442**Result** ✓ Passed**MOT #12** 2018-09-05 14:20**MOT test number** 761857247388**Result** ✓ Passed**MOT #11** 2017-09-06 09:00**MOT test number** 529230931916**Result** ✓ Passed**Advice** Plastic covers not allowing full inspection of some components under car**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2016-09-08 11:20**MOT test number** 447584493620**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2015-09-03 14:42**MOT test number** 557653261871**Result** ✓ Passed

**MOT #8** 2015-09-03 00:00**MOT test number** 479196037105**Result** ✗ Failed**Fail** Offside Rear Service brake grabbing severely (3.7.C.2)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick inner (3.5.1g)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2014-09-10 14:52**MOT test number** 608713854217**Result** ✓ Passed**MOT #6** 2013-09-04 11:11**MOT test number** 147507243272**Result** ✓ Passed**MOT #5** 2012-09-11 16:56**MOT test number** 296555152226**Result** ✓ Passed**MOT #4** 2012-09-11 16:56**MOT test number** 965895952295**Result** ✗ Failed**Pass with rectification** Offside Rear fog lamp not working (1.3.2b)**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)

**MOT #3** 2011-09-01 11:22**MOT test number** 756104841233**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Front brake disc's worn
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2010-09-14 16:28**MOT test number** 714417050258**Result** ✓ Passed**MOT #1** 2010-09-14 08:39**MOT test number** 554637650258**Result** ✗ Failed

- Fail** Service brake: efficiency below requirements (3.7.B.7)
- Fail** Brake performance not tested (3.7.A.1)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Parking brake lever defective so that it cannot be satisfactorily operated (3.1.3c)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
7 June 2024

Tax status		Valid until 1 July
Days left		63
MOT expiry date		7 June 2024
Full MOT history		See MOT history

Tax calculation

Vehicle class	49
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-07-31
Last registration	2023-05-24
Complete history	See info



Registration #1	2007-07-31	9 mi
Registration #2	2010-09-14	26.878 mi
Registration #3	2010-09-14	26.878 mi
Registration #4	2011-09-01	41.847 mi
Registration #5	2012-09-11	49.757 mi
Registration #6	2013-09-04	56.663 mi
Registration #7	2014-09-10	60.698 mi
Registration #8	2015-09-03	64.903 mi
Registration #9	2015-09-03	64.910 mi
Registration #10	2016-09-08	69.474 mi
Registration #11	2016-09-08	69.474 mi
Registration #12	2016-09-08	69.474 mi
Registration #13	2016-09-08	69.474 mi
Registration #14	2016-09-08	69.474 mi
Registration #15	2016-09-08	69.474 mi
Registration #16	2016-09-08	69.474 mi
Registration #17	2016-09-08	69.474 mi
Registration #18	2016-09-08	69.474 mi
Registration #19	2016-09-08	69.474 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2230 mm
Height	1726 mm
Length	4754 mm
Wheel base	2855 mm
Max. allowed weight	2850 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	BPE 011134