





report date: 2024-03-28

General information

| Make | VOLVO |
|---------------------|-------------------------------------|
| Model | XC90 D5 POWERPULSE R-DESIGN PRO AWD |
| Colour | Silver |
| Year of manufacture | 2018 |
| Top speed | 137 mph |
| 0 - 60 mph | 7.4 seconds |
| Gearbox | 8 speed automatic |

Engine & fuel consumption

| Power | 231 BHP |
|---------------------------------|---------------------|
| Max. torque | 480 Nm at 1.750 rpm |
| Engine capacity | 1.969 сс |
| Cylinders | 4 |
| | |
| Fuel type | Diesel |
| Fuel type Consumption combined | Diesel 35.3 mpg |
| • | 2.000 |



CarCheck.co.uk page 1/10



report date: 2024-03-28

Internet history

Entry 1

| Date | 2021-02-06 |
|---------------|-------------|
| Pictures | 1 |
| Listing price | View report |



source: autoonline.co.uk

CarCheck.co.uk page 2/10



report date: 2024-03-28

MOT history

MOT expiry date 2025-01-25

CarCheck.co.uk page 3/10



report date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 February |
|------------------|------------------------|
| Days left | 278 |
| MOT expiry date | 25 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|--|--------------|
| Band | I |
| First licence fee (12 months) | £ 645,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 1.040,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 4/10



report date: 2024-03-28

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-28

| _ | |
|--------|----------|
| Owner | hictory |
| OWITCH | HIISLOHY |

| For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full r | |
|---|--|
| | |
| | |
| | |
| | |
| ******* | |
| *************************************** | |
| ************* | |
| | More info > |
| Plate changes | |
| See in this check if this VOLVO had different number plates. | |
| Number of plates | |
| Current registration | NK SIE |
| Plate since | |
| Current registration | UK NAME OF THE PROPERTY OF THE |
| Plate since | |
| | More info > |

CarCheck.co.uk page 7/10



report date: 2024-03-28

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-28

Mileage check

| Mileage registrations | 2 |
|----------------------------|------------|
| First mileage registration | 2018-09-01 |
| Complete history | See info |



| Registration #1 | 2018-09-01 | 20 mi |
|-----------------|------------|-----------|
| Registration #2 | | D. 777 44 |

Registration #2

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-28

Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 50482 | |
| 50501 | |
| 60566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 97% |
| Children | 87% |
| Pedestrian | 72% |
| Safety systems | 94% |
| Overall rating | 89% |
| Video | see crash video |



Dimensions & weight

| Width | 2008 mm |
|---------------------|---------|
| Height | 1776 mm |
| Length | 4950 mm |
| Wheel base | 2984 mm |
| Kerb weight | 2009 kg |
| Max. allowed weight | 2750 kg |

Additional information

| Fuel tank capacity | 71 |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 7 page 10/10 |

Number of axles2Engine number2551350