



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO MATCH (70BHP)
Colour	Silver
Year of manufacture	2009
Top speed	104 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Max. torque	112 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	138 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-02-26
Pictures	15
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-12-05
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	30
Total items failed	1

MOT #20	2023-11-27 16:15
MOT test number	526595051622
Result	✓ Passed
Next expiry date	2024-12-05

MOT #19	2023-11-27 11:25
MOT test number	713181644973
Result	✗ Failed
DANGEROUS	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
DANGEROUS	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #18	2022-11-16 10:20
MOT test number	394866851493
Result	✓ Passed
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Handbrake high

**MOT #17**

2021-12-06 17:30

MOT test number

574997966228

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Rear corrosion to exhaust box outer cover

MOT #16

2021-11-23 15:13

MOT test number

902287818917

Result

✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
- MAJOR** Front Exhaust has a major leak of exhaust gases down pipe flexi (6.1.2 (a))
- MAJOR** Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))
- Advice** Rear corrosion to exhaust box outer cover
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- MAJOR** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

**MOT #15** 2021-02-12 09:02**MOT test number** 484112632720**Result** Passed**MOT #14** 2021-02-11 13:08**MOT test number** 161753234509**Result** Failed**MAJOR** Nearside Side repeater not working (4.4.1 (a) (ii))**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #13** 2020-01-22 14:41**MOT test number** 734475661564**Result** Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #12** 2020-01-20 10:57**MOT test number** 208699596523**Result** Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Central Exhaust system insecure (6.1.2 (a))**MOT #11** 2019-01-23 15:31**MOT test number** 762843007522**Result** Passed

**MOT #10** 2019-01-15 15:32**MOT test number** 927634067903**Result** ✗ Failed**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #9** 2018-01-19 14:01**MOT test number** 853200508160**Result** ✓ Passed**MOT #8** 2017-01-14 10:29**MOT test number** 935739410148**Result** ✓ Passed**MOT #7** 2016-09-12 08:07**MOT test number** 796164603987**Result** ✓ Passed**MOT #6** 2016-09-12 08:07**MOT test number** 818255047790**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #5** 2016-03-14 11:22**MOT test number** 262234665880**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin both sides 3/4 worn (3.5.1g)



MOT #4	2015-03-02 12:55
MOT test number	518901265036
Result	✓ Passed
MOT #3	2014-03-05 12:48
MOT test number	999024764026
Result	✓ Passed
MOT #2	2013-03-14 10:37
MOT test number	517423573072
Result	✓ Passed
MOT #1	2012-03-06 14:36
MOT test number	169886762038
Result	✓ Passed
Advice	Parking brake lever has little reserve travel (3.1.6b)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
5 December 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	5 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-




Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2024-03-29
Current registration	 *****
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2009-03-16
Last registration	2023-11-27
Complete history	See info



Registration #1	2009-03-16	7 mi
Registration #2	2012-03-06	22.112 mi
Registration #3	2013-03-14	31.473 mi
Registration #4	2014-03-05	39.233 mi
Registration #5	2015-03-02	45.943 mi
Registration #6	2016-03-14	52.011 mi
Registration #7	2016-09-12	54.661 mi
Registration #8	2016-09-12	54.661 mi
Registration #9	2017-01-14	54.742 mi
Registration #10	2018-01-19	61.480 mi
Registration #11	2019-01-15	68.760 mi
Registration #12	2019-01-15	68.760 mi
Registration #13	2019-01-15	68.760 mi
Registration #14	2019-01-15	68.760 mi
Registration #15	2019-01-15	68.760 mi
Registration #16	2019-01-15	68.760 mi
Registration #17	2019-01-15	68.760 mi
Registration #18	2019-01-15	68.760 mi
Registration #19	2019-01-15	68.760 mi
Registration #20	2019-01-15	68.760 mi
Registration #21	2019-01-15	68.760 mi
Registration #22	2019-01-15	68.760 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

BZG258667