





report date: 2024-03-29

## General information

Make	VOLKSWAGEN	
Model	CC GT TDI BLUEMOTION TECHNOLOGY	
Colour	White	
Year of manufacture	2015	
Top speed	145 mph	
Gearbox	6 speed Manual	

# Engine & fuel consumption

Power	182 BHP
Max. torque	380 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	55.4 mpg
CO2 emission	127 g/km
CO2 label	D



CarCheck.co.uk page 1/12



report date: 2024-03-29

# Internet history

### Entry 3

Date 2024-02-12

Pictures 0

Listing price <u>View report</u>

### source: carcraft.co.uk

### Entry 2

Date 2024-02-07


Pictures 28

Listing price <u>View report</u>









#### source: cargurus.co.uk

### Entry 1

Date 2021-10-02

Pictures 5

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



V065ECV report date: 2024-03-29

MOT history

MOT expiry date	2024-10-24
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	13
Total items failed	2

MOT #8		2023-10-23 08:34
MOT test	number	415822389286
Result		✓ Passed
Next expi	ry date	2024-10-24
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7	2022-10-25 10:59
MOT test number	654279831856
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



**Advice** 

VO65ECV

report date: 2024-03-29

**MOT #6** 2022-10-25 08:14 **MOT** test number 590888039950 Result × Failed Fail Offside Front Service brake excessively fluctuating (1.2.1 (e)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Front tyre worn heavily on inner edge almost to cords Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) Fail **Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Offside Front Tyre worn close to legal limit/worn on edge on legal limit of 1.6mm (5.2.3 (e)) Advice **Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #5

MOT test number

So3227514894

Result

✓ Passed

MOT #4

MOT test number

896532748037

Result

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #3

MOT test number

Result

Advice

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #2 2018-11-23 15:55

**MOT test number** 738329572046

**Result** ✓ Passed

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #1** 2017-11-14 15:44

**MOT test number** 619870136777

Result 

Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 5/12



V065ECV report date: 2024-03-29

## Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	24 October 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

## Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



### Extra VOLKSWAGEN salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



VO65ECV report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



VO65ECV report date: 2024-03-29

Owner history

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Downere.	
*********	
***********	
********	
***************************************	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NE UK
Plate since	990.0
Current registration	OK SIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



VO65ECV report date: 2024-03-29

## Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 

 $\quad \text{More info} \quad > \quad$ 

CarCheck.co.uk page 10/12



VO65ECV report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-12-16
Last registration	2023-10-23
Complete history	See info



Registration #1	2015-12-16	13 mi
Registration #2	2017-11-14	11.378 mi
Registration #3	2018-11-23	16.724 mi
Registration #4	2019-11-21	21.042 mi
Registration #5	2020-10-27	24.678 mi
Registration #6		77.777 46
Registration #7		11.777 es
Registration #8		77.777 46
Registration #9		11.777 es
Registration #10		77.777 46
Registration #11		11.777 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

## Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
60567	
50569	

# Dimensions & weight

Width	1855 mm
Height	1421 mm
Length	4802 mm
Wheel base	2710 mm
Kerb weight	1590 kg
Max. allowed weight	2130 kg

# Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	CUWA302201

CarCheck.co.uk page 12/12