





report date: 2024-03-29

General information

Make	HYUNDAI
Model	140 CRDI PREMIUM
Colour	Silver
Year of manufacture	2012
Top speed	124 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	325 Nm at 2.500 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	61.4 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E



CarCheck.co.uk page 1/11



B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-06-28
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	11
Total items failed	3

MOT #11	2023-06-29 13:34
MOT test number	223276096894
Result	✓ Passed
Next expiry date	2024-06-28

MOT #	#10	2023-06-26 17:03
MOT t	est number	309137188491
Resul	t en	X Failed
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Fail	Driver's seat backrest cannot be secured in the upright position. (6.2.5 (b) (ii))	

MOT #9		2022-06-28 14:05
MOT test	number	906361987117
Result		✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 2/11



MOT #8 2021-06-17 07:00

MOT test number 662634003981

MOT #7 2020-06-23 11:09

MOT test number 533383061121

Result ✓ Passed

Minor Nearside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #6 2020-06-23 11:09

MOT test number 322559210973

Result X Failed

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b)

(ii))

Minor

Nearside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #5 2019-05-28 11:53

MOT test number 649422593370

Result ✓ Passed

MOT #4 2018-06-15 13:39

MOT test number 366103592498

CarCheck.co.uk page 3/11



MOT #3 2017-08-21 11:05

MOT test number 288559190375

Result ✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #2 2016-08-23 09:02

MOT test number 149522844104

Result \rightarrow Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #1 2015-08-29 08:50

MOT test number 492806760686

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	28 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

Owner mistory	
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	OK OK
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-09-01
Last registration	2023-06-29
Complete history	See info



Registration #1	2012-09-01	27 mi
Registration #2	2015-08-29	15.675 mi
Registration #3	2016-08-23	20.640 mi
Registration #4	2017-08-21	25.555 mi
Registration #5	2018-06-15	29.582 mi
Registration #6	2019-05-28	34.868 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		0.777-46

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4740 mm
Wheel base	2770 mm
Kerb weight	1610 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles 2

Engine number D4FDCU098604