



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	TUCSON CRDI SE NAV BLUE DRIVE
Colour	Blue
Year of manufacture	2017
Top speed	115 mph
0 - 60 mph	11.5 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	139 BHP
Max. torque	340 Nm at 2.500 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	60.1 mpg
Consumption combined	57.6 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-01-31
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-03-25
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	11
Total items failed	0

MOT #7	2024-03-26 15:22
MOT test number	489516324534
Result	✓ Passed
Next expiry date	2025-03-25

MOT #6	2024-03-21 14:29
MOT test number	103311204531
Result	✗ Failed
 DANGEROUS Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #5	2023-03-09 08:39
MOT test number	998760468582
Result	✓ Passed
 Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #4	2022-03-23 08:47
MOT test number	909504360923
Result	✓ Passed

MOT #3	2021-03-24 17:00
MOT test number	698718510698
Result	✓ Passed



MOT #2 2020-10-14 14:16

MOT test number 950858519901

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm and side wall damaged (5.2.3 (e))

Advice Nearside Rear Bumper damaged

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

MOT #1 2020-10-14 10:12

MOT test number 660064065863

Result ✗ Failed

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Bumper damaged

Advice Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

MAJOR Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords plus unrepairable puncture (5.2.3 (d) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm and side wall damaged (5.2.3 (e))



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
25 March 2025

Tax status	Valid until 1 February
Days left	279
MOT expiry date	25 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-11-10
Last registration	2024-03-26
Complete history	See info



Registration #1	2017-11-10	27 mi
Registration #2	2020-10-14	28.171 mi
Registration #3	2020-10-14	28.175 mi
Registration #4	2020-10-14	28.177 mi
Registration #5	2021-03-24	29.230 mi
Registration #6	2021-03-24	29.232 mi
Registration #7	2021-03-24	29.234 mi
Registration #8	2021-03-24	29.236 mi
Registration #9	2021-03-24	29.238 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	85%
Pedestrian	71%
Safety systems	71%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1850 mm
Height	1650 mm
Length	4475 mm
Wheel base	2670 mm
Kerb weight	1470 kg
Max. allowed weight	2085 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

D4FDHZ667810