





report date: 2024-03-28

## General information

Make	VAUXHALL
Model	MERIVA SE
Colour	Silver
Year of manufacture	2014
Top speed	110 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	99 BHP
Max. torque	130 Nm at 4.000 rpm
Engine capacity	1.398 сс
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	140 g/km
CO2 label	E



CarCheck.co.uk page 1/11



report date: 2024-03-28

# Internet history

#### Entry 1

Date	2021-09-11	
Pictures	1	
Listing price	<u>View report</u>	



source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

# MOT history

MOT expiry date	2024-08-10
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	2
Total items failed	2

MOT #9	2023-07-24 11:10
MOT test number	670448066025
Result	<b>✓</b> Passed
Next expiry date	2024-08-10
Advice Front Upper Macpherson strut pin or bush worn but not resulting in esides 2nd yr (5.3.4 (a) (i))	excessive movement both

MOT #8	2022-07-22 11:40
MOT test number	459329526559
Result	✓ Passed
Advice Front Upper Shock absorbers has a slightly worn bush both sides (5.3.2 (c))	

MOT #7	2021-07-13 09:30
MOT test number	363463817946
Result	✓ Passed
MOT #6	2021-07-13 09:30
MOT test number	822275542955
Result	<b>▼</b> Failed
Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #5	2020-07-14 12:28
MOT test number	591614510460
Result	<b>✓</b> Passed
MOT #4	2019-07-16 10:25
MOT test number	791826347177
Result	<b>✓</b> Passed

 MOT #3
 2019-07-16 10:25

 MOT test number
 459224707417

Result X Failed

Pass with rectification (h))

Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3  $\,$ 

MOT #2	2018-07-27 09:06
MOT test number	408076429275
Result	<b>✓</b> Passed

MOT #1	2017-08-11 08:43
MOT test number	768919109686
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	10 August 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

## Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date

Category

**Type** 

Damage 2

Category

Date

Type



#### Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

## Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

# Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloahere.	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	IK SINS
Plate since	
Current registration	NE NE
Plate since	
	Moro info

CarCheck.co.uk page 8/11



report date: 2024-03-28

## Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-09-30
Last registration	2023-07-24
Complete history	See info



Registration #1	2014-09-30	26 mi
Registration #2	2017-08-11	8.153 mi
Registration #3	2018-07-27	10.643 mi
Registration #4	2019-07-16	13.713 mi
Registration #5	2019-07-16	13.713 mi
Registration #6	2020-07-14	15.857 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 mg

More info >

CarCheck.co.uk page 10/11



YR64HBX report date: 2024-03-28

# Safety ratings

NCAP rating	****
Adult	89%
Children	77%
Pedestrian	55%
Safety systems	86%
Overall rating	80%
Video	see crash video



# Dimensions & weight

Width	1994 mm
Height	1615 mm
Length	4300 mm
Wheel base	2644 mm
Kerb weight	1376 kg
Max. allowed weight	1905 kg

# Additional information

Fuel tank capacity	54
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B14XER -19FK0822LDD

CarCheck.co.uk page 11/11