



HYUNDAI



MW59VEU

report date: 2024-03-29

General information

Make	HYUNDAI
Model	I800 CRDI STYLE
Colour	Silver
Year of manufacture	2010
Top speed	112 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	392 Nm at 2.000 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	39.8 mpg
Consumption combined	33.2 mpg
CO2 emission	225 g/km
CO2 label	K







Internet history

Entry 1

Date	2021-12-12
Pictures	17
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-01-31
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	38
Total items failed	6

MOT #14	2023-01-04 15:37
MOT test number	113111246712
Result	✓ Passed
Next expiry date	2024-01-31
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #13	2022-12-22 10:53
MOT test number	826279174079
Result	✗ Failed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))
MAJOR	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
MAJOR	Brake lever has abnormal movement of levers indicating excessive wear or maladjustment (1.1.15 (f))

MOT #12	2022-01-06 10:33
MOT test number	513217405031
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2021-01-09 08:03**MOT test number** 982463822161**Result** ✓ Passed**MOT #10** 2020-01-29 12:57**MOT test number** 187109855981**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Minor** Rear Stop lamp(s) switch does not operate in accordance with the requirements (4.3.2 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Central Child Seat fitted not allowing full inspection of adult belt n/s & os**Advice** Brake pedal wearing smooth (1.1.2 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #9** 2019-01-15 12:33**MOT test number** 611981394097**Result** ✓ Passed**MOT #8** 2019-01-07 08:09**MOT test number** 196878323038**Result** ✗ Failed**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #7** 2018-01-31 16:35**MOT test number** 704602108572**Result** ✓ Passed



MOT #6	2017-01-19 07:50
MOT test number	110985850201
Result	✓ Passed

MOT #5	2016-02-01 09:56
MOT test number	434639603602
Result	✓ Passed
Advice	Front brake discs worn
Advice	Rear heater pipes corroded/leaking
Advice	Turbo inter/cooler leaking

MOT #4	2016-02-01 09:56
MOT test number	983093914334
Result	✗ Failed
Advice	Turbo inter/cooler leaking
Advice	Front brake discs worn
Advice	Rear heater pipes corroded/leaking
Pass with rectification	Registration plate lamp not working both sides (1.1.C.1d)



MOT #3

2015-01-21 16:22

MOT test number

545811525066

Result

✓ Passed

- Notice

Engine covers fitted obscuring some components in the engine bay
- Notice

H/brake travel high
- Advice

Nearside Rear reflector slightly damaged but function not impaired (1.5.1c)
- Notice

Under-trays fitted obscuring some underside components
- Notice

Nail in offside rear tyre
- Notice

Front brake discs worn
- Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice

Child seat fitted not allowing full inspection of adult belt

**MOT #2**

2015-01-21 13:20

MOT test number

739491425028

Result**✗ Failed**

- Fail** Centre Seat belt retracting mechanism defective (5.2.5b)
- Notice** Front brake discs worn
- Fail** Offside passenger door cannot be opened from outside the vehicle (6.2.B.1c)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear reflector slightly damaged but function not impaired (1.5.1c)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)
- Notice** H/brake travel high
- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Under-trays fitted obscuring some underside components
- Fail** Front position lamp(s) not working (1.1.A.3b)
- Notice** Nail in offside rear tyre

MOT #1

2014-01-21 12:36

MOT test number

397241324090

Result**✓ Passed**

- Notice** Handbrake travel high



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-01-29
Last registration	2023-01-04
Complete history	See info



Registration #1	2010-01-29	18 mi
Registration #2	2014-01-21	60.733 mi
Registration #3	2015-01-21	80.444 mi
Registration #4	2015-01-21	80.446 mi
Registration #5	2016-02-01	98.485 mi
Registration #6	2016-02-01	98.485 mi
Registration #7	2017-01-19	103.276 mi
Registration #8	2018-01-31	112.966 mi
Registration #9	2019-01-01	121.277 mi
Registration #10	2019-01-01	121.277 mi
Registration #11	2019-01-01	121.277 mi
Registration #12	2019-01-01	121.277 mi
Registration #13	2019-01-01	121.277 mi
Registration #14	2019-01-01	121.277 mi
Registration #15	2019-01-01	121.277 mi
Registration #16	2023-01-04	121.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5125 mm
Wheel base	3200 mm
Kerb weight	2270 kg
Max. allowed weight	3030 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8

Number of axles	2
Engine number	D4CBA626086