



S067BKX

report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | MAZDA |
| Model | 3 SE-L NAV |
| Colour | White |
| Year of manufacture | 2017 |
| Top speed | 121 mph |
| 0 - 60 mph | 8.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 118 BHP |
| Max. torque | 210 Nm at 4.000 rpm |
| Engine capacity | 1.998 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 43.5 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 55.4 mpg |
| CO2 emission | 119 g/km |
| CO2 label | C |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-10-15 |
| Pictures | 0 |
| Listing price | View report |

source: heycar.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-10-30 |
| MOT pass rate | 67 % |
| MOT passed | 4 |
| Failed MOT tests | 2 |
| Total advice items | 11 |
| Total items failed | 2 |

MOT #6 2023-10-31 12:48**MOT test number** 987478150764**Result** ✓ Passed**Next expiry date** 2024-10-30**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened BOTH (1.1.14 (a) (ii))**Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #5** 2022-10-15 14:34**MOT test number** 565464958574**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 215/45/R18, 3mm tread (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing 215/45/R18 (5.2.3 (d) (ii))**MOT #4** 2022-10-15 08:09**MOT test number** 586892932448**Result** ✗ Failed**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 215/45/R18, 3mm tread (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing 215/45/R18 (5.2.3 (d) (ii))

**MOT #3** 2021-10-22 15:01**MOT test number** 599061444286**Result** ✓ Passed

Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords Outer sidewall. (5.2.3 (d) (i))

MOT #2 2020-10-05 08:29**MOT test number** 588956487473**Result** ✓ Passed

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #1 2020-10-05 08:29**MOT test number** 267726944210**Result** ✗ Failed

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Pass with rectification Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
30 October 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 November |
| Days left | 186 |
| MOT expiry date | 30 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--------------------------------------|------------|
| Vehicle class | 48 |
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

| | |
|----------|--|
| Damage 1 | |
| Date | |
| Category | |
| Type | |
| Damage 2 | |
| Date | |
| Category | |
| Type | |



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this MAZDA had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2019-06-29 |
| Current registration | ***** |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 8 |
| First mileage registration | 2017-10-14 |
| Last registration | 2023-10-31 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2017-10-14 | 23 mi |
| Registration #2 | 2020-10-05 | 29.829 mi |
| Registration #3 | 2020-10-05 | 29.829 mi |
| Registration #4 | 2020-10-05 | 29.829 mi |
| Registration #5 | 2020-10-05 | 29.829 mi |
| Registration #6 | 2020-10-05 | 29.829 mi |
| Registration #7 | 2020-10-05 | 29.829 mi |
| Registration #8 | 2020-10-05 | 29.829 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 93% |
| Children | 86% |
| Pedestrian | 65% |
| Safety systems | 81% |
| Overall rating | 85% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1795 mm |
| Height | 1465 mm |
| Length | 4465 mm |
| Wheel base | 2700 mm |
| Kerb weight | 1351 kg |
| Max. allowed weight | 1815 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 51 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | PE 20877374 |