



report date: 2024-03-28

General information

Make	VOLVO
Model	V70 V70 D5 SE
Colour	Silver
Year of manufacture	2005
Top speed	130 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.9 mpg
CO2 emission	209 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-05-21
Pictures	21
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-01
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	14
Total items failed	10

MOT #18	2023-11-02 12:01
MOT test number	894293925384
Result	✓ Passed
Next expiry date	2024-11-01
Minor	Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
Minor	Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #17	2023-11-02 12:01
MOT test number	701779716962
Result	✗ Failed
Minor	Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
Pass with rectification	Central Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Minor	Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))

**MOT #16** 2022-12-12 10:21**MOT test number** 830504031312**Result** ✓ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15 2021-12-09 10:06**MOT test number** 240567130637**Result** ✓ Passed**MOT #14** 2021-12-08 13:24**MOT test number** 296033737202**Result** ✗ Failed

Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #13 2020-11-02 11:10**MOT test number** 973619803321**Result** ✓ Passed

Advice Nearside Rear Suspension component corroded but not seriously weakened trail arm mount (5.3.3 (b) (i))

Advice Offside Rear Suspension component corroded but not seriously weakened trail arm mount (5.3.3 (b) (i))

MOT #12 2018-11-14 15:05**MOT test number** 969589266424**Result** ✓ Passed

**MOT #11** 2018-11-13 16:38**MOT test number** 900670317865**Result** ✗ Failed**Fail** Front Windscreen washer not working (3.5 (a))**MOT #10** 2017-03-15 12:31**MOT test number** 634219744288**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #9** 2016-01-15 11:13**MOT test number** 598506783632**Result** ✓ Passed**MOT #8** 2014-07-18 14:02**MOT test number** 709499994129**Result** ✓ Passed**MOT #7** 2012-12-17 17:14**MOT test number** 359102852337**Result** ✓ Passed**MOT #6** 2012-12-07 14:58**MOT test number** 557962642349**Result** ✗ Failed**Fail** Rear Exhaust system not adequately supported (7.1.1)**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)

**MOT #5** 2011-12-08 15:13**MOT test number** 218622241332**Result** ✓ Passed**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**MOT #4** 2010-12-17 14:14**MOT test number** 783231350394**Result** ✓ Passed**MOT #3** 2010-12-14 09:38**MOT test number** 584288540394**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Centre Rear Exhaust system not adequately supported (7.1.1)**MOT #2** 2009-11-10 13:14**MOT test number** 743854219322**Result** ✓ Passed**MOT #1** 2008-09-08 15:01**MOT test number** 871022458201**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
1 November 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	1 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	NT55KKD
Plate since	2024-03-28
Current registration	NT55KKD
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-09-09
Last registration	2023-11-02
Complete history	See info



Registration #1	2005-09-09	20 mi
Registration #2	2008-09-08	18.285 mi
Registration #3	2009-11-10	24.889 mi
Registration #4	2010-12-14	31.330 mi
Registration #5	2010-12-17	31.330 mi
Registration #6	2011-12-08	34.136 mi
Registration #7	2012-12-07	39.743 mi
Registration #8	2012-12-17	39.743 mi
Registration #9	2014-07-18	46.088 mi
Registration #10	2016-01-15	49.820 mi
Registration #11	2016-01-15	49.820 mi
Registration #12	2016-01-15	49.820 mi
Registration #13	2016-01-15	49.820 mi
Registration #14	2016-01-15	49.820 mi
Registration #15	2016-01-15	49.820 mi
Registration #16	2016-01-15	49.820 mi
Registration #17	2016-01-15	49.820 mi
Registration #18	2016-01-15	49.820 mi
Registration #19	2016-01-15	49.820 mi
Registration #20	2016-01-15	49.820 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1720 mm
Height	1400 mm
Length	4520 mm
Wheel base	2560 mm
Kerb weight	1427 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	291390