





report date: 2024-03-28

### General information

Make	BMW
Model	114 114D SPORT
Colour	Black
Year of manufacture	2014
Top speed	115 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	94 BHP
Max. torque	235 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	56.5 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	112 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-28

## Internet history

### Entry 1

Date 2021-09-22

Pictures 14

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-07-20
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	17
Total items failed	5

MOT #9	2023-06-29 14:06
MOT test number	363921972248
Result	<b>✓</b> Passed
Next expiry date	2024-07-20
Advice Offside Front Suspension arm pin or bush worn but not resulting lower arm front bush (5.3.4 (a) (i))	g in excessive movement front
Advice Nearside Front Suspension arm pin or bush worn but not resulting lower arm front bush (5.3.4 (a) (i))	ng in excessive movement front

MOT #8		2022-07-21 15:16
MOT test	number	457848956732
Result		✓ Passed
Advice	Rear Oil leak, but not excessive rear diff oil leak (8.4.1 (a) (i))	
Advice (i))	Offside Front Steering rack has slight free play detected at steering wheel in	nner track rod (2.3 (a)

MOT #7		2021-07-06 14:23
MOT test	number	367330013873
Result		✓ Passed
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excessive move	ement (5.3.4 (a)
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive mo	vement (5.3.4
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



608584677175

**MOT #6** 2020-09-25 13:04

Result \( \sqrt{Passed} \)

Advice

**MOT** test number

Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #5 2019-09-20 12:08

**MOT test number** 976297650737

**Result** ✓ Passed

MOT #4 2019-09-18 13:31

**MOT test number** 927440780197

Result X Failed

**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MAJOR** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords sidewall (5.2.3 (d) (i))

**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MAJOR** Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #3 2018-09-05 11:24

MOT test number 206627522701

Result 

Passed

**Advice** Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))

MOT #2 2017-09-06 11:26


MOT test number 855540210059

**Result** 
✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28



CarCheck.co.uk page 5/12



report date: 2024-03-28

# Tax & MOT check



Tax status	Valid until 1 November
Days left	187
MOT expiry date	20 July 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Dainage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra BMW salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner	hictor,
UWNEI	nisioiv
OWINCE	THISCOLY

o met motory	
For how long did the current and previous owner(s) have this BMW? How many owners defect it in the premium report and see all owner registrations. Download the full report	
********	
***************************************	
THE STREET STREET	
*********	
***************************************	
THE PROPERTY OF THE PROPERTY O	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	OK STEE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-07-31
Last registration	2023-06-29
Complete history	See info



Registration #1	2014-07-31	11 mi
Registration #2	2017-08-29	53.772 mi
Registration #3	2017-09-06	53.786 mi
Registration #4	2018-09-05	65.923 mi
Registration #5	2019-09-18	73.765 mi
Registration #6	2019-09-20	73.848 mi
Registration #7		11.777 es
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.177 es

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditionin
60295	
60482	
60501	
60566	
0567	
60569	

# Safety ratings

NCAP rating	****
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	see crash video



# Dimensions & weight

Width	1765 mm
Height	1421 mm
Length	4324 mm
Wheel base	2690 mm
Kerb weight	1315 kg
Max. allowed weight	1880 kg

### Additional information

Fuel tank capacity	52 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 12/

Number of axles 2

Engine number 75379091