



Mercedes-Benz

MAI3SCZ

report date: 2024-03-29

General information

| | |
|---------------------|---------------------|
| Make | MERCEDES-BENZ |
| Model | ML ML250 BLUETEC SE |
| Colour | Black |
| Year of manufacture | 2013 |
| Top speed | 130 mph |
| 0 - 100 km/h | 9.0 seconds |
| 0 - 60 mph | 9.0 seconds |
| Gearbox | 7 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------------|
| Power | 150 kW / 204 HP / 204 BHP |
| Max. torque | 500 Nm at 1.800 rpm |
| Engine capacity | 2.143 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 38.7 mpg |
| Consumption extra urban | 50.4 mpg |
| Consumption combined | 44.8 mpg |
| CO2 emission | 165 g/km |
| CO2 label | G |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-09-25 |
| Pictures | 32 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-09-09 |
| MOT pass rate | 90 % |
| MOT passed | 9 |
| Failed MOT tests | 1 |
| Total advice items | 10 |
| Total items failed | 2 |

| | |
|------------------|------------------|
| MOT #10 | 2023-08-31 10:45 |
| MOT test number | 769552156660 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-09 |

| | |
|-----------------|--|
| MOT #9 | 2022-09-08 11:26 |
| MOT test number | 639680503707 |
| Result | ✓ Passed |
| Minor | Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) |

| | |
|-----------------|--|
| MOT #8 | 2021-08-24 13:27 |
| MOT test number | 128983063909 |
| Result | ✓ Passed |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Minor | Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) |

**MOT #7** 2020-09-10 09:34**MOT test number** 971183354456**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2020-09-04 11:37**MOT test number** 330692826647**Result** ✗ Failed**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2019-08-30 11:22**MOT test number** 171556951134**Result** ✓ Passed**MOT #4** 2018-09-04 08:19**MOT test number** 372765233080**Result** ✓ Passed**MOT #3** 2017-10-12 16:12**MOT test number** 295083377158**Result** ✓ Passed



| | |
|-----------------|-------------------------------|
| MOT #2 | 2016-10-13 09:23 |
| MOT test number | 831373560079 |
| Result | ✓ Passed |
| Advice | Emissions too clean to record |

| | |
|-----------------|------------------|
| MOT #1 | 2015-10-19 15:56 |
| MOT test number | 808050931352 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
9 September 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 October |
| Days left | 154 |
| MOT expiry date | 9 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 7 |
| Current registration | MA13SCZ |
| Plate since | 2019-06-29 |
| Current registration | MA13SCZ |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 12 |
| First mileage registration | 2013-03-30 |
| Last registration | 2023-08-31 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2013-03-30 | 7 mi |
| Registration #2 | 2015-10-19 | 10.846 mi |
| Registration #3 | 2016-10-13 | 19.207 mi |
| Registration #4 | 2017-10-12 | 33.700 mi |
| Registration #5 | 2018-09-04 | 42.457 mi |
| Registration #6 | 2019-08-30 | 55.615 mi |
| Registration #7 | 2019-08-30 | 55.615 mi |
| Registration #8 | 2019-08-30 | 55.615 mi |
| Registration #9 | 2019-08-30 | 55.615 mi |
| Registration #10 | 2019-08-30 | 55.615 mi |
| Registration #11 | 2019-08-30 | 55.615 mi |
| Registration #12 | 2019-08-30 | 55.615 mi |

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Dimensions & weight

| | |
|---------------------|---------|
| Width | 1998 mm |
| Height | 1796 mm |
| Length | 4804 mm |
| Wheel base | 2915 mm |
| Kerb weight | 2150 kg |
| Max. allowed weight | 2950 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 70 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 65196031474778 |