





report date: 2024-03-28

General information

Make	AUDI
Model	A8 TDI QUATTRO SPORT
Colour	Silver
Year of manufacture	2008
Top speed	151 mph
0 - 60 mph	8.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	229 BHP
Max. torque	450 Nm at 3.250 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Diesel
Consumption city	22.8 mpg
Consumption extra urban	41.5 mpg
Consumption combined	32.1 mpg
CO2 emission	224 g/km
CO2 label	K



CarCheck.co.uk page 1/14



report date: 2024-03-28

Internet history

Entry 1

Date 2021-05-25

Pictures 26

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-05-04
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	38
Total items failed	1

MOT #16	2023-05-05 10:01
MOT test number	215623709717
Result	✓ Passed
Next expiry date	2024-05-04

MOT #15		2022-04-14 13:48
MOT test	number	743022421577
Result		✓ Passed
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2	2.3 (d) (i))

MOT #14	2021-05-05 12:50
MOT test number	763601072534
Result	✓ Passed
Advice Offside Front Upper Suspension arm pin or bush worn but not re rear (5.3.4 (a) (i)) Advice Offside Front Upper Suspension arm pin or bush worn but not re	
front (5.3.4 (a) (i))	saiting in excessive movement

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT #13 2021-04-28 12:09

MOT test number 969950139942

Result X Failed

MAJOR Offside Side repeater not working (4.4.1 (a) (ii))

Advice Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement front (5.3.4 (a) (i))

Advice Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Nearside Front Upper Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))

Advice Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement front (5.3.4 (a) (i))

DANGEROUS Nearside Front Inner Tyre has a bulge, caused by separation or partial failure of its structure sidewall (5.2.3 (d) (ii))

MOT #12 2020-04-01 13:27

MOT test number 895382470435

Result \(\sqrt{Passed} \)

Advice Nearside Front Mirror casing damaged no sharp edge

Advice Front Upper Suspension arm pin or bush worn but not resulting in excessive movement X2 Both sides (5.3.4 (a) (i))

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT #11 2020-03-26 12:15 **MOT** test number 303508712966 Result **X** Failed **MAJOR** Exhaust emits excessive dense blue smoke during acceleration (8.2.1.2 (g)) **MAJOR** Nearside Front Inner Track rod end ball joint has excessive play (2.1.3 (b) (i)) Front Outer Track rod end ball joint has excessive play X2 (2.1.3 (b) (i)) **MAJOR MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) Advice Nearside Front Mirror casing damaged no sharp edge Advice Front Upper Suspension arm pin or bush worn but not resulting in excessive movement X2 Both sides (5.3.4 (a) (i)) **MAJOR** Offside Front Inner Track rod end ball joint has excessive play (2.1.3 (b) (i)) **MAJOR** Offside Rear Service brake excessively fluctuating (1.2.1 (e))

MOT #10 2019-03-27 15:28 334596327013 **MOT** test number Result Passed **MOT #9** 2019-03-25 17:08 **MOT** test number 798941101730 Result × Failed **MAJOR** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #8	2018-03-27 10:05
MOT test number	214578866038
Result	✓ Passed
Advice E.M.L	

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #7 2017-01-27 11:16

MOT test number 359149913721

Result ✓ Passed

Advice

EML on dash

MOT #6 2016-02-20 11:40

MOT test number 952717565276

Result ✓ Passed

Advice Nearside Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement cracking (2.4.G.2)

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement centre (2.4.G.2)

Advice EML On dash

Advice Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

Advice Offside Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement Cracking (2.4.G.2)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement centre (2.4.G.2)

MOT #5 2016-02-20 10:51

MOT test number 120551037321

Result X Failed

CarCheck.co.uk page 6/14

Advice Nearside Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement cracking (2.4.G.2)

Advice Nearside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement centre (2.4.G.2)

Advice Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

Advice Offside Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement Cracking (2.4.G.2)

Advice EML On dash

Fail Offside Front Anti-roll bar linkage rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement centre (2.4.G.2)



GF58ZXZ report date: 2024-03-28

 MOT #4
 2015-01-22 11:55

 MOT test number
 288772225032

 Result
 ✓ Passed

Notice Engine management lamp on indicating a fault

MOT #3 2014-01-13 14:50

MOT test number 877223214095

Result ✓ Passed

 MOT #2
 2012-12-20 15:28

 MOT test number
 669985852334

 Result
 ✓ Passed

 MOT #1
 2011-11-30 12:21

 MOT test number
 485074331401

CarCheck.co.uk page 7/14



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	4 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

Owner	history
O WILCI	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,

e when this test	
For how long did the current and previous owner(s) have this AUDI? How many owners of Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	
Current registration	NK NE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-28

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-12-17
Last registration	2023-05-05
Complete history	See info



Registration #1	2008-12-17	26 mi
Registration #2	2011-11-30	30.598 mi
Registration #3	2012-12-20	38.641 mi
Registration #4	2014-01-13	47.824 mi
Registration #5	2015-01-22	56.022 mi
Registration #6	2016-02-20	66.614 mi
Registration #7	2016-02-20	66.614 mi
Registration #8	2017-01-27	74.479 mi
Registration #9	2018-03-27	84.563 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91,709 esi
Registration #16		11.777 es
Registration #17		11.772 es
Registration #18		0.00 44

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

Car features

50225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	2028 mm
Height	1455 mm
Length	5181 mm
Wheel base	3074 mm
Kerb weight	1740 kg
Max. allowed weight	2430 kg

Additional information

Fuel tank capacity	90
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	ASB 090101

CarCheck.co.uk page 14/14