





report date: 2024-03-29

#### General information

Make	CITROEN	
Model	C4 CACTUS PURETECH TOUCH	
Colour	Silver	
Year of manufacture	2017	
Top speed	106 mph	
0 - 60 mph	12.9 seconds	
Gearbox	5 speed Manual	

## Engine & fuel consumption

Power	74 BHP	
Max. torque	118 Nm at 2.750 rpm	
Engine capacity	1.200 cc	
Cylinders	3	
Fuel type	Petrol	
Consumption city	50.4 mpg	
Consumption extra urban	70.6 mpg	
Consumption combined	61.4 mpg	
CO2 emission	105 g/km	
CO2 label	В	



CarCheck.co.uk page 1/11



report date: 2024-03-29

## Internet history

#### Entry 1

Date 2021-01-29

Pictures 9

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

# MOT history

MOT expiry date	2024-08-13
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	15
Total items failed	1

MOT #5		2023-08-11 10:53
MOT test	number	391811318953
Result		✓ Passed
Next expi	ry date	2024-08-13
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on 3mm (5.2.3	(e))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Advice Front Brake disc worn, pitted or scored, but not seriously weakened discs lipping (1.1.14 (a) (ii))	
Advice	Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	

MOT #4	2022-08-01 12:33
MOT test number	585597616464
Result	✓ Passed
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #3	2022-08-01 09:40
MOT test number	352050138001
Result	<b>×</b> Failed
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Fail Nearside Front Outer Tyre has ply or cords exposed side (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

**MOT** #2 2021-07-30 09:06 865417775682 **MOT** test number ✓ Passed Result **Advice** Items removed from driver's view prior to test Advice Nearside front tyre has outer sidewall damage Advice Front Sub-frame corroded but not seriously weakened corrosion on top side (5.3.3 (b) (i)) Advice Rear Brake disc worn, pitted or scored, but not seriously weakened s)(mainly inner surfaces (1.1.14 (a) (ii)) Advice Rear axle corroded Advice Oil leak, but not excessive (8.4.1 (a) (i)) Advice Brake hose has slight corrosion to ferrule multiple unions/connections corroding (1.1.12 (f) (i)) Handbrake lever has little remaining reserve travel Advice

MOT #1	2020-07-23 11:27
MOT test number	763903322151
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	13 August 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

SA17AFM

report date: 2024-03-29

# For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report here. More info >

#### Plate changes

See in this check if this CITROEN had different number plates.

More info >

CarCheck.co.uk page 8/11



SA17AFM report date: 2024-03-29

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-08-14
Last registration	2023-08-11
Complete history	See info



Registration #1	2017-08-14	19 mi
Registration #2	2020-07-23	4.687 mi
Registration #3		11.777 es
Registration #4	2021-07-30	11.422 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 esi

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

# Safety ratings

NCAP rating	****
Adult	82%
Children	79%
Pedestrian	80%
Safety systems	56%
Overall rating	76%
Video	see crash video

# Dimensions & weight

Width	1729 mm
Height	1480 mm
Length	4157 mm
Wheel base	2595 mm
Kerb weight	965 kg
Max. allowed weight	1500 kg

# Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B2150463309

CarCheck.co.uk page 11/11