





report date: 2024-03-28

General information

Make	CITROEN	
Model	BERLINGO 625 XTR PLUS L1 HDI	
Colour	Red	
Year of manufacture	2013	
Top speed	99 mph	
0 - 60 mph	12.8 seconds	
Gearbox	5 speed Manual	

Engine & fuel consumption

Power	90 BHP
Max. torque	215 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption combined	53.3 mpg
	33.3 pg
CO2 emission	138 g/km



CarCheck.co.uk page 1/11



report date: 2024-03-28

MOT history

MOT expiry date	2025-01-21
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	15
Total items failed	11

MOT #12	2024-01-22 16:27
MOT test number	268321551634
Result	✓ Passed
Next expiry date	2025-01-21
Advice Slight play at o/s/f ball joint	
Advice Front discs corroded	

MOT #11	2024-01-18 11:02
MOT test number	855589321145
Result	🗙 Failed
Fail Offside Front Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))	
Advice Front discs corroded	
Fail Nearside Front Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))	

MOT #10	2023-01-19 11:38
MOT test number	200029798735
Result	✓ Passed
MOT #9	2022-01-18 16:08
MOT test number	834676249670

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT #8 2021-02-19 14:47

MOT test number 712495263469

Result
✓ Passed

MOT #7 2021-02-19 14:47

MOT test number 397704309594

Result X Failed

Pass with rectification Offside Headlamp aim too low (4.1.2 (a))

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #6 2019-06-13 15:51

MOT test number 981950077040

Result \(\sqrt{Passed} \)

Advice Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Slight bearing noise

MOT #5 2019-05-30 15:49

MOT test number 485162592206

Result X Failed

Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Slight bearing noise

Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Offside Headlamp levelling device inoperative (4.1.5 (a))

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Nearside Front Position lamp not working (4.2.1 (a))

CarCheck.co.uk page 3/11



report date: 2024-03-28

 MOT #4
 2018-06-01 13:54

 MOT test number
 408814118535

 Result
 ✓ Passed

 MOT #3
 2018-05-31 08:59

 MOT test number
 222908261314

 Result
 X Failed

 Fail
 Nearside Front Brake hose excessively twisted (1.1.12 (b) (ii))

MOT #2 2017-05-20 10:48 **MOT** test number 421219207019 Result ✓ Passed **Advice** Central Front Inner Brake pad(s) wearing thin (3.5.1g) **Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a) Advice Nearside Rear some brake grab **Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) **Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a) Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d) Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #1	2016-05-05 09:56
MOT test number	518662896946
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	21 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this CITROEN had different number plates. about of pliates furthe scinors

CarCheck.co.uk page 8/11



SH13BYF
report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-05-24
Last registration	2024-01-22
Complete history	See info



Registration #1	2013-05-24	23 mi
Registration #2	2016-05-05	31.405 mi
Registration #3	2017-05-20	48.300 mi
Registration #4	2018-05-31	63.840 mi
Registration #5	2018-06-01	63.856 mi
Registration #6	2019-05-30	85.764 mi
Registration #7	2019-06-13	86.584 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.777 ms
Registration #12		0.00 44
Registration #13		

More info >

CarCheck.co.uk page 10/11



SH13BYF report date: 2024-03-28

Safety ratings

NCAP rating	dokakak
Video	see crash video



Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	JBEM0144600

CarCheck.co.uk page 11/11