



PEUGEOT

MK52WND


report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 D P/V
Colour	Silver
Year of manufacture	2002
Gearbox	4 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	at 2.500 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
CO2 emission	191 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-05-22
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-05-23
MOT pass rate	71 %
MOT passed	20
Failed MOT tests	8
Total advice items	42
Total items failed	17

MOT #28 2023-05-17 14:36

MOT test number 609016041722

Result ✓ Passed

Next expiry date 2024-05-23

Advice Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #27 2022-05-24 09:15

MOT test number 222552667270

Result ✓ Passed

MOT #26 2022-05-21 12:17

MOT test number 198025957662

Result ✗ Failed

Fail Front Windscreen wiper blade missing (3.4 (b) (ii))

Fail Nearside Side repeater incorrect colour (4.4.3 (a))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Offside Side repeater incorrect colour (4.4.3 (a))

Fail Horn not working (7.7 (a))



MOT #25	2021-05-14 07:05
MOT test number	296063587723
Result	✓ Passed

MOT #24	2020-01-11 12:19
MOT test number	349110806228
Result	✓ Passed

- Advice** Rear exhaust system corroded
- Advice** Chip in windscreen zone a
- Advice** Both rear tyres perished and slightly cut outer wall
- Advice** Offside fuel tank strap corroded
- Advice** Offside Front tyre 2mm and slightly wear inner edge
- Advice** Slightly power steering oil weap from all pipes

**MOT #23**

2020-01-11 09:56

MOT test number

484606116994

Result

✗ Failed

- Advice** Both rear tyres perished and slightly cut outer wall
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Offside fuel tank strap corroded
- Advice** Chip in windscreen zone a
- Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Offside Front tyre 2mm and slightly wear inner edge
- Advice** Slightly power steering oil weap from all pipes
- Advice** Rear exhaust system corroded
- Fail** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #22

2019-01-02 10:07

MOT test number

285687028923

Result

✓ Passed

- Advice** Play in steering rack inner joint(s) both sides
- Advice** Offside fuel tank strap rusty
- Advice** Both rear tyres slightly cut outer wall
- Advice** Chip in windscreen swept area

**MOT #21**

2019-01-02 10:07

MOT test number

389614810543

Result**✗ Failed****Advice**

Both rear tyres slightly cut outer wall

Advice

Chip in windscreen swept area

Advice

Play in steering rack inner joint(s) both sides

Pass with rectification

Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice

Offside fuel tank strap rusty

MOT #20

2018-01-13 09:25

MOT test number

533625240673

Result**✓ Passed****Advice**

Nearside Front Outer Tyre wall cut, not showing cords

Advice

Offside Front Upper Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice

Center section to rear exhaust silencer badly corroded

MOT #19

2016-12-30 13:07

MOT test number

450919517421

Result**✓ Passed****Advice**

Offside Play in steering rack inner joint(s)

Advice

O/s fuel tank strap rusty

Advice

Nearside Play in steering rack inner joint(s)

**MOT #18**

2016-12-30 09:26

MOT test number

391592493694

Result**✗ Failed**

- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Nearside Rear Rear position lamp(s) slightly affected by the operation of another lamp (1.1.A.3f)
- Fail** Nearside Front Direction indicators incorrect colour (1.4.A.2f)
- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Offside Play in steering rack inner joint(s)
- Fail** Offside Front Direction indicators incorrect colour (1.4.A.2f)
- Advice** O/s fuel tank strap rusty
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #17

2016-01-12 10:00

MOT test number

190540483301

Result**✓ Passed****MOT #16**

2016-01-12 10:00

MOT test number

238367189988

Result**✗ Failed**

- Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #15

2015-01-12 09:52

MOT test number

899712315089

Result**✓ Passed**

- Notice** Exhaust rusty
- Notice** Both rear tyres perished

**MOT #14** 2014-01-16 10:58**MOT test number** 665026214024**Result** ✓ Passed**Notice** Nearside rear tyre slight perishing**MOT #13** 2014-01-16 10:58**MOT test number** 498366014005**Result** ✗ Failed**Pass with rectification** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**Notice** Nearside rear tyre slight perishing**MOT #12** 2013-05-10 11:53**MOT test number** 199220933189**Result** ✓ Passed**MOT #11** 2013-05-10 11:29**MOT test number** 818210533140**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2013-05-09 08:55**MOT test number** 299879623476**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #9** 2013-02-11 11:19**MOT test number** 319392143018**Result** ✓ Passed

**MOT #8** 2013-02-11 11:19**MOT test number** 695592843025**Result** ✗ Failed**Pass with rectification** Rear Exhaust has a major leak of exhaust gases (7.1.2)**MOT #7** 2012-02-24 09:45**MOT test number** 359535852023**Result** ✓ Passed**MOT #6** 2011-02-24 10:07**MOT test number** 298965151037**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2010-02-25 10:21**MOT test number** 131946950035**Result** ✓ Passed**MOT #4** 2009-02-02 15:13**MOT test number** 601253839025**Result** ✓ Passed**Notice** Headlamp masks/converters fitted**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2008-07-02 15:26**MOT test number** 421634288187**Result** ✓ Passed



MOT #2	2007-06-28 09:51
MOT test number	460519377109
Result	✓ Passed
MOT #1	2006-07-05 13:59
MOT test number	400576986113
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
23 May 2024

Tax status	Valid until 1 January
Days left	248
MOT expiry date	23 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2002-09-01
Last registration	2023-05-17
Complete history	See info



Registration #1	2002-09-01	27 mi
Registration #2	2006-07-05	26.150 mi
Registration #3	2007-06-28	33.990 mi
Registration #4	2008-07-02	42.765 mi
Registration #5	2009-02-02	44.211 mi
Registration #6	2010-02-25	48.461 mi
Registration #7	2011-02-24	52.587 mi
Registration #8	2012-02-24	57.578 mi
Registration #9	2013-02-11	62.717 mi
Registration #10	2013-05-09	62.971 mi
Registration #11	2013-05-10	62.971 mi
Registration #12	2013-05-10	95.202 mi
Registration #13	2014-01-16	64.682 mi
Registration #14	2015-01-12	65.124 mi
Registration #15	2015-05-20	75.377 mi
Registration #16	2015-05-20	75.377 mi
Registration #17	2015-05-20	75.377 mi
Registration #18	2015-05-20	75.377 mi
Registration #19	2015-05-20	75.377 mi
Registration #20	2015-05-20	75.377 mi
Registration #21	2015-05-20	75.377 mi
Registration #22	2015-05-20	75.377 mi
Registration #23	2015-05-20	75.377 mi
Registration #24	2015-05-20	75.377 mi
Registration #25	2015-05-20	75.377 mi
Registration #26	2015-05-20	75.377 mi

Registration #27	2020-05-20	20,000,000
Registration #28	2020-05-20	20,000,000

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Additional information

Fuel delivery	Indirect Injection
Number of axles	2
Engine number	NOT KNOWN