



**BN06KNP**

report date: 2024-03-28

General information

Make	NISSAN
Model	ALMERA
Colour	Black
Year of manufacture	-
Gearbox	-

Engine & fuel consumption

Fuel type	Petrol
-----------	--------



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-22
Pictures	4
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #20</b>	2020-10-26 14:51
<b>MOT test number</b>	695895249519
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2021-10-26
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
<b>Advice</b>	Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Offside Rear Coil spring corroded (5.3.1 (b) (i))
<b>Minor</b>	Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

<b>MOT #19</b>	2020-10-26 09:23
<b>MOT test number</b>	445835127384
<b>Result</b>	✗ Failed
<b>Fail</b>	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
<b>Advice</b>	Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
<b>Minor</b>	Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
<b>Advice</b>	Offside Rear Coil spring corroded (5.3.1 (b) (i))
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Fail</b>	Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
<b>Advice</b>	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Fail</b>	Front Service brake excessively fluctuating by 30kgf on both front (1.2.1 (e))

**MOT #18**

2019-04-23 12:08

**MOT test number**

214214158077

**Result**

✓ Passed

**Advice**

Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords Tyre perished (5.2.3 (d) (i))

**Advice**

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Offside Rear Tyre has a cut but not deep enough to reach the ply or cords Tyre perished (5.2.3 (d) (i))

**Minor**

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #17**

2019-04-18 09:01

**MOT test number**

429567917275

**Result**

✗ Failed

**Fail**

Nearside Front Position lamp not working (4.2.1 (a))

**Minor**

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Fail**

Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**Fail**

Offside Front Service brake excessively binding (1.2.1 (f))

**Fail**

Offside Front Position lamp not working (4.2.1 (a))

**Advice**

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail**

Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**MOT #16**

2018-04-27 13:46

**MOT test number**

584818141127

**Result**

✓ Passed

**MOT #15** 2018-04-25 15:12**MOT test number** 942303788394**Result** ✗ Failed**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Emissions not tested (7.3.A.1)**MOT #14** 2016-09-30 07:26**MOT test number** 196756840918**Result** ✓ Passed**Advice** Slight brake bind o/s/front**MOT #13** 2015-10-05 10:10**MOT test number** 791400824186**Result** ✓ Passed**MOT #12** 2014-05-15 10:39**MOT test number** 849045634193**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #11** 2013-05-31 15:13**MOT test number** 175921353109**Result** ✓ Passed**Notice** Advise tracking**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #10** 2013-05-29 12:24**MOT test number** 176109043186**Result** ✗ Failed**Fail** Driver's airbag obviously defective (5.4.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Advise tracking**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Passenger's airbag obviously defective (5.4.1)**MOT #9** 2012-06-12 09:45**MOT test number** 779124762115**Result** ✓ Passed**MOT #8** 2012-06-09 11:17**MOT test number** 239771562480**Result** ✗ Failed**Fail** Parking brake lever has no reserve travel (3.1.6b)**MOT #7** 2011-05-30 10:43**MOT test number** 428930351153**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #6** 2011-05-30 10:43**MOT test number** 998790951126**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #5** 2011-05-11 16:48**MOT test number** 259481331413**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Fail** Offside Side repeater missing (1.4.A.2b)**Notice** Offside rear tyre pressure low**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Body has a sharp edge caused by damage (6.1.C.1)**MOT #4** 2010-05-14 09:18**MOT test number** 780174730113**Result** ✓ Passed**Notice** Offside indicator side repeater lense missing**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2010-05-13 16:31**MOT test number** 581453030199**Result** ✗ Failed**Fail** Front registration plate delaminated (6.3.1d)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Offside indicator side repeater lense missing**Fail** Rear registration plate delaminated (6.3.1d)**MOT #2** 2009-04-07 09:41**MOT test number** 161197999446**Result** ✓ Passed



MOT #1	2008-04-15 12:27
MOT test number	251056508444
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)





Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-03-27
Last registration	2020-10-26
Complete history	<a href="#">See info</a>



Registration #1	2006-03-27	17 mi
Registration #2	2008-04-15	7.231 mi
Registration #3	2009-04-07	21.320 mi
Registration #4	2010-05-13	34.200 mi
Registration #5	2010-05-14	34.200 mi
Registration #6	2011-05-11	43.852 mi
Registration #7	2011-05-30	44.176 mi
Registration #8	2012-06-09	52.277 mi
Registration #9	2012-06-12	522.314 mi
Registration #10	2013-05-29	54.576 mi
Registration #11	2013-05-31	54.614 mi
Registration #12	2014-06-01	55.277 mi
Registration #13	2014-06-01	55.277 mi
Registration #14	2014-06-01	55.277 mi
Registration #15	2014-06-01	55.277 mi
Registration #16	2014-06-01	55.277 mi
Registration #17	2014-06-01	55.277 mi
Registration #18	2014-06-01	55.277 mi
Registration #19	2014-06-01	55.277 mi
Registration #20	2014-06-01	55.277 mi
Registration #21	2014-06-01	55.277 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Additional information

Engine number GA16-566159