





report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	GLA GLA 200 D SPORT EXECUTIVE
Colour	White
Year of manufacture	2016
Top speed	127 mph
0 - 100 km/h	7.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 kW / 177 HP / 134 BHP
Max. torque	350 Nm at 1.400 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	56.5 mpg
Consumption extra urban	80.7 mpg
Consumption combined	67.3 mpg
CO2 emission	110 g/km
CO2 label	В



CarCheck.co.uk page 1/11



CK16AKZ

report date: 2024-03-29

Internet history

Entry 2

Date 2021-06-23

Pictures 34

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-06-22

Pictures 34

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-05-25
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	12
Total items failed	4

MOT #6		2023-05-26 13:56
MOT test	number	810211103467
Result		✓ Passed
Next expi	ry date	2024-05-25
Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))		
Advice	Nearside Rear Brake pad(s) wearing thin inner pad (1.1.13 (a) (ii))	

MOT #5		2022-03-29 15:43
MOT test	number	199924667078
Result		✓ Passed
Advice	Nearside Rear Brake pad(s) wearing thin inner pad (1.1.13 (a) (ii))	
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #4	2021-03-10 16:58
MOT test	number 570556642471
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing Starting to perish. (5.2.3 (d) (ii))
Advice Offside Rear Tyre slightly damaged/cracking or perishing Starting to perish. (5.2.3 (d) (ii))	
Advice	Child Seat fitted not allowing full inspection of adult belt N/s/front & o/s/rear.

CarCheck.co.uk page 3/11



Passed

MOT #3 2021-03-10 12:21

MOT test number 728130298837

Result X Failed

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing Starting to perish. (5.2.3 (d) (ii))

Advice Child Seat fitted not allowing full inspection of adult belt N/s/front & o/s/rear.

Advice Tyre Pressure Monitor light on - Amber

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing Starting to perish. (5.2.3 (d) (ii))

MOT #2 2020-03-03 07:14

MOT test number 147935956108

Result

Passed

MOT #1 2019-03-29 15:51

MOT test number 683648437119

003040437113

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Result

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	25 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11




Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra MERCEDES-BENZ salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

Owner matery	
For how long did the current and previous owner(s) have this MERCEDES-BENZ? How material MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. It report here.	
PROPERTY.	

	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	OK SIZ
Plate since	
Current registration	UK NA
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-03-31
Last registration	2023-05-26
Complete history	See info



Registration #1	2016-03-31	23 mi
Registration #2	2019-03-29	37.288 mi
Registration #3	2020-03-03	48.531 mi
Registration #4	2021-03-10	64.847 mi
Registration #5	2021-03-10	64.847 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	93%
Children	81%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1804 mm
Height	1494 mm
Length	4417 mm
Wheel base	2699 mm
Kerb weight	1505 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack caluk	nago 11/11

CarCheck.co.uk page 11/11

Number of seats	5
Number of axles	2
Engine number	65193033426300